



SAFEGUARDS INFORMATION

UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION II

101 MARIETTA ST., N.W., SUITE 3100

ATLANTA, GEORGIA 30303

JUL 12 1983

Report Nos. 50-335/83-25 and 50-389/83-50

Docket Nos. 50-335 and 50-389

License Nos. DPR-67 and NPF-16

Licensee: Florida Power and Light Company
9250 West Flager Street
Miami, FL 33408

Facility Name: St. Lucie 2

Inspection at: Ft. Pierce, FL

Inspection conducted: June 13-15, 1983

Date of Last Physical Security Inspection Visit: May 23-27, 1983

Type of Inspection: Special Physical Security

Inspector: D. E. Moore 7/11/83
D. E. Moore, Physical Security Inspector Date Signed

Approved by: D. R. McGuire 7/11/83
D. R. McGuire, Chief, Physical Security Section Date Signed
Safeguards Branch, Division of Emergency
Preparedness and Materials Safety Programs

Inspection Summary

Areas Inspected: Included review of the Physical Security Plan and Implementing Procedures relative to Records and Reports, Physical Barriers-Vital Areas and Access Control-Personnel in response to incidents reported by the resident inspector and the licensee.

The inspection involved 16 inspector hours on site by one NRC inspector. The inspection was begun during an offshift period.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during the inspection.

ENCLOSURE CONTAINS
SAFEGUARDS INFORMATION.
UPON SEPARATION THIS
PAGE IS DECONTROLLED.

8307150355 830712
PDR ADOCK 05000335
Q PDR

SAFEGUARDS INFORMATION