



Environmental Restoration Group, Inc.
12809 Arroyo de Vista NE
Albuquerque, New Mexico 87111
(505) 298-4224

September 21, 1994

RP

40-8902

Mr. Joseph Holonich, Branch Chief
United States Nuclear Regulatory Commission
Uranium Recovery Branch
Division of Low-Level Waste Management
and Decommissioning, NMSS (5 E2)
11555 Rockville Pike
Rockville, MD 20850

Dear Mr. Holonich:

At the request of Mr. Ken Hooks and Elaine Brummett, I am providing information on a project where we made radon flux measurements under the direction of the U. S. EPA. Our radon flux measurement procedures and canister description were incorporated in a CERCLA site work plan. The work plan, "Soil Cover Depth Work Plan", October 1993, prepared by Roy F. Weston, Inc. for Stauffer Management Company, Tarpon Springs, Florida, was reviewed and approved by the U. S. EPA. Mr. Maxwell Kimpson (404-347-2643) was the EPA Project Manager.

Please advise me if you need additional information.

Sincerely,

Kenneth R. Baker

Kenneth R. Baker, Ph. D.
Principal

9410070175 940921
PDR ADDCK 04008902
E PDR

*NL05
1/0*

ERG

Environmental Restoration Group, Inc.
12809 Arroyo de Vista NE
Albuquerque, New Mexico 87111



Mr Joseph Kolomich, Branch Chief
U.S. NRC
Waste Recovery Branch
Division of Low-Level Waste Management
and Decommissioning, NMS5 (5E2)
11555 Rockville Pike
Rockville, MD 20850

int

