



Testing • Inspection • Consultation
Engineering Services

The Haller Testing Laboratories of Massachusetts, Inc.

BOSTON AREA TEL (617) 235 8032
WORCESTER AREA TEL (617) 366 0937

P O BOX 381 11A WALKUP DR WESTBOROUGH MASS 01581

August 3, 1987

Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pa. 19406

Attn: Mr. Thomas Martin, Director
Gentlemen:

Re: License #20-13722-01
EA - 146

In reply to your letter of July 17, 1987 relative to inspection #030-04760/87-01 Appendix 'A' be advised of the following corrective steps which have been taken as of this date.

A. Upon returning to the laboratory from a job site the Troxler portable moisture density gauge is immediately removed from the truck and put under proper storage facilities.

B. A chain and padlock has been installed in the transportation vehicle to prevent movement within the vehicle.

All of the above have been completed as of August 3 1987.

Very truly yours

THE HALLER TESTING LABORATORIES
OF MASSACHUSETTS, INC.


Robert L. Macee, P.E.

88 2 11 8-00V 1801

8710080168 XA 871003

H/57