ALLADOC INFOD

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-341/84-02(DRMSP)

Docket No. 50-341

License No. CPPR-87

Licensee: Detroit Edison Company 2000 Second Avenue Detroit, MI 48226

Facility Name: Enrico Fermi Atomic Power Plant, Unit 2

Inspection At: Plant Site

Inspection Conducted: January 10-13, 1984

Date of Last Physical Security Inspection: September 26-30, 1983

Type of Inspection: Announced, Pre-Operational Physical Protection

Inspectors: T. J. Madeda

Physical Protection Specialist

A. W. Stepleton Physical Protection Specialist

2/1/84 Date 2/1/84

2/1/84

R. Creed, Chief afeguards Section

Approved By:

Inspection Summary

Inspection on January 10-13, 1984 (Report No. 50-341/84-02[DRMSP])

8402060009 840201 PDR ADDCK 05000341

Areas Inspected: Included a review of the status of implementation, installation, operability of the security program, and the preoperational testing program for security-related equipment. Specifically, the inspection covered: Security Plan and Implementing Procedures; Security Organization - Management; Security Program Audit; Testing and Maintenance; Physical Barriers - Protected Areas and Vital Areas; Lighting; Access Control - Personnel, Packages, and Vehicles; Detection Aids - Protected Areas and Vital Areas; Alarm Stations;

> Enclosure Contains SAUCCHARDS INFORMATION Upon Separation This Paga is Decontrolled

SAFEGUARDS INFURMATION

SAFEQUARDS INFORMATION

General Requirements T&Q Plan; Additional Requirements - Power Reactors; and Safeguards Information. This inspection involved 58 inspector-hours onsite by two NRC inspectors.

<u>Results:</u> Based on the preoperational inspection, the inspectors determined the status of areas within the security program and identified areas that must be completed prior to fuel load. No items of noncompliance were identified.

Enclosure Conta is SAFERMARDS INFORMATION Upon Separation This Page is Decontrolled