

U. S. NUCLEAR REGULATORY COMMISSION
REGION I

Report No. 50-322/92-02

Docket No. 50-322

License No. NPF-82

License: Long Island Lighting Company
P. O. Box 618
Shoreham Nuclear Power Station
Wading River, New York 11792

Facility Name: Shoreham Nuclear Power Station

Inspection At: Wading River, New York

Inspection Conducted: February 20, 1992

Inspector: *D. F. Limroth* 3.11.92
D. F. Limroth, Sr. Reactor Engineer date

Approved by: *R. R. Keimig* 3/11/92
R. R. Keimig, Chief, Safeguards Section date
Division of Radiation Safety and Safeguards

Areas Inspected: Security Program Plans; Management Support; Protected Area Physical Barriers and Detection Aids; Protected Area Access Control of Personnel; and Alarm Stations and Communications

Results: The licensee was found to be in compliance with NRC requirements in the areas inspected.

DETAILS

1.0 Personnel Contacted

The inspector met with Mr. A. Downs, Nuclear Security Division Manager, and interviewed members of the licensee and contractor security organization. Due to the limited scope of this inspection, no formal exit interview was conducted; however, the findings of the inspection were discussed with Mr. Downs prior to the inspector's departure from the station.

2.0 Purpose and Scope of Inspection

Following the issuance of a possession only license, on February 17, 1992, the licensee implemented a revised physical security plan (the Plan) commensurate with the significantly reduced scope of operations of the station. The purpose of this inspection was to ensure that the changes in the Plan had been satisfactorily implemented.

3.0 Management Support

Management support for the licensee's physical security program was determined to be adequate by the inspector. This determination was based upon the inspector's review of the various aspects of the licensee's program as documented in this inspection report.

4.0 Protected Area Physical Barriers and Detection Aids

The inspector conducted a physical inspection of the protected area (PA) barriers and determined that barriers were installed and maintained as described in the Plan. The inspector also inspected the PA detection aids and determined that they were installed and operated as committed to in the Plan. No deficiencies were noted.

5.0 Protected Area Access Control of Personnel

The inspector determined that the licensee was exercising positive control over personnel access to the PA. This determination was based on the following:

- The inspector verified that personnel are properly identified, and authorization is checked, prior to issuance of badges and keycards. No deficiencies were noted.
- The inspector verified that the licensee has a search program, as committed to in the Plan, for firearms, explosives, incendiary devices and other unauthorized materials. The inspector observed personnel access processing, including visitor processing, and interviewed members of the security force and licensee's security staff about personnel access procedures.

- The inspector determined, by observation, that individuals in the PA display their access badges as required. No deficiencies were noted.
- The inspector verified that the licensee had escort procedures for visitors to the PA. No deficiencies were noted.

6.0 Alarm Station and Communications

The inspectors observed the operations of the Central Alarm Station (CAS) and determined that it was maintained and operated as committed to in the Plan. The CAS operator interviewed by the inspector was found to be knowledgeable of her duties and responsibilities. The inspectors verified that the CAS does not contain any operational functions that would interfere with the assessment and response functions. No deficiencies were noted.