



SAFEGUARDS INFORMATION  
UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30303

APR 11 1984

Report Nos. 50-369/84-08 and 50-370/84-08

Docket Nos. 50-369 and 50-370

License Nos. NPF-9 and NPF-17

Licensee: Duke Power Company  
422 South Church Street  
Charlotte, NC 28242

Facility Name: McGuire 1 and 2

Inspection at: McGuire site near Lake Norman, NC

Inspection conducted: March 25-29, 1984

Date of Last Physical Security Inspection Visit: July 23-29, 1983

Type of Inspection: Unannounced Physical Security

Inspector: D. E. Moore  
D. E. Moore, Physical Security Inspector

4/10/84  
Date Signed

Approved by: D. R. McGuire  
D. R. McGuire, Chief, Physical Security Section  
Safeguards Branch, Division of Emergency  
Preparedness and Materials Safety Programs

4/10/84  
Date Signed

Inspection Summary

Inspection Included: Review of Security Plan and Implementing Procedures; Security Organization - Personnel and Response; Security Program Audit; Testing and Maintenance; Physical Barriers - Protected and Vital Areas; Security System Power Supply; Assessment Aids; Access Control - Personnel, Packages, and Vehicles; Detection Aides - Protected and Vital Areas; Alarm Stations; Communications; and Followup on Previous Enforcement Matters.

The inspection involved 39 inspector hours on site by one NRC inspector. The inspection was begun during an offshift period. Four hours were accomplished during offshift periods.

Results: The licensee was found to be in compliance with NRC requirements within the areas examined during the inspection except for the following item:

Failure to provide complete intrusion detection capability at the protected area boundary.

8406050275 840411  
PDR ADDCK 05000369  
Q PDR

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION.  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED.

SAFEGUARDS INFORMATION