

Northeast
Utilities System

107 Selden Street, Berlin, CT 06037

Northeast Utilities Service Company
P.O. Box 270
Hartford, CT 06141-0270
(203) 665-5000

September 7, 1995

Docket No. 50-423
B15366

Re: 10CFR50.55a(g)

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555


Millstone Nuclear Power Station, Unit No. 3
In-Service Inspection Summary Report

In accordance with 10CFR50.55a(g) and ASME Code Section XI, IWA-6230, "Summary Report Submittals," Northeast Nuclear Energy Company is providing the Staff with a copy of the Millstone Nuclear Power Station, Unit No. 3, In-Service Inspection Summary Report. Attached to this letter is a copy of the In-Service Inspection Summary Report for the Millstone Unit No. 3 1995 Refueling Outage.

We hope you find this information satisfactory, and we remain available to answer any questions you may have. If you should have any questions, please contact Mr. R. G. Joshi at (203) 440-2080.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY



J. F. Opeka
Executive Vice President

Attachment

cc: T. T. Martin, Region I Administrator
V. L. Rooney, NRC Project Manager, Millstone Unit No. 3
P. D. Swetland, Senior Resident Inspector, Millstone Unit
Nos. 1, 2, and 3

120033

Adm
44