



**Commonwealth Edison**  
LaSalle County Nuclear Station  
Rural Route #1, Box 220  
Marseilles, Illinois 61341  
Telephone 815/357-6761


*DMB*

June 19, 1984

Mr. James G. Keppler  
Regional Administrator  
Region III  
U.S. Nuclear Regulatory Commission  
799 Roosevelt Road  
Glen Ellyn, IL 60137

Dear Mr. Keppler:

In accordance with LaSalle County Station Unit 1 Facility Operating License NPF-11, Appendix B, Section 3.2, we are submitting to you a copy of the NPDES noncompliance for LaSalle County Nuclear Generating Station Permit No. IL0048151.

  
G. J. Diederich  
Station Superintendent

GJD/FRL/SKD/kg

Enclosure

xc: DVR Report

JUN 29 1984

B407160170 B40619  
PDR ADOCK 05000373  
S PDR

*IF01*



Commonwealth Edison  
LaSalle County Nuclear Station  
Rural Route #1, Box 220  
Marselles, Illinois 61341  
Telephone 815/357-6761

June 4, 1984

U.S. Environmental Protection Agency  
Region V, Enforcement Division  
ATTN: Chief, Compliance Unit  
230 South Dearborn Street  
Chicago, IL 60604


Illinois Environmental Protection Agency  
Division of Water Pollution Control  
Compliance Management Unit  
2200 Churchill Road  
Springfield, IL 62706

Dear Sir:

Subject: NPDES Noncompliances for LaSalle County Nuclear  
Generating Station - Permit No. IL0048151

In accordance with Standard Condition 12, we wish to submit the following notice of a noncompliance which is listed on the attached table.

If there are any questions, please contact Steve Davis of my staff at (815) 357-6761, extension 487.

  
G. J. Diederich  
Station Superintendent

GJD/FRL/SKD/bej

xc: Director of Water Quality, Environmental Affairs  
Manager, Nuclear Stations Division

LASALLE COUNTY NUCLEAR GENERATING STATION  
N.P.D.E.S. PERMIT NO: IL0048151  
NONCOMPLIANCE REPORT

DISCHARGE NUMBER AND DESCRIPTION: 001c Wastewater Treatment Facility Effluent

PARAMETER AND PERMIT LIMIT: pH, 6.0 - 9.0 S.U.

NONCOMPLIANCE, DATE, AND DURATION: 9.8 S.U., 30MAY84, unknown (believed to be less than 8 hours)

CAUSE OF NONCOMPLIANCE: The MUD clean sump was sampled and analyzed for pH on 30MAY84. The 11.2 S.U. result indicated the sump was the source of the high pH water. The original source is unknown.

CORRECTIVE ACTION: The discharge was stopped. The clearwell was circulated back to the equalization tank and neutralized. Resamples were drawn at 1630 on 01JUN84. The results indicated the clearwell pH was 9.0 S.U. and the equalization tank was 7.6 S.U. Wastewater Treatment Facility operations were then returned to normal.

DATE RECOGNIZED AS A VIOLATION:

30MAY84

DATE INVESTIGATED:

30MAY84