



# SAFEGUARDS INFORMATION

UNITED STATES  
NUCLEAR REGULATORY COMMISSION

REGION II  
101 MARIETTA STREET, N.W.  
ATLANTA, GEORGIA 30303

JUL 30 1984

Report Nos. 50-335/84-24 and 50-389/84-26

Licensee: Florida Power and Light Company  
9250 West Flagler Street  
Miami, FL 33102

Docket Nos. 50-335 and 50-389

License Nos. DPR-67 and NPF-16

Facility Name: St. Lucie 1 and 2

Inspection Date: July 9-13, 1984

Inspector: *A. Fillman* 7/25/84  
A. Fillman, Physical Security Inspector Date Signed

Approved by: *D. R. McGuire* 7/27/84  
D. R. McGuire, Chief, Physical Security Section Date Signed  
Nuclear Materials Safety and Safeguards Branch  
Division of Radiation Safety and Safeguards

### SUMMARY

Scope: This routine unannounced inspection entailed 30 inspector-hours on site (two hours on backshift) inspecting: changes to the approved physical security plan and implementing procedures; security program audit; testing and maintenance; physical barriers; security system power supply; assessment aids; access controls; and detection aids.

Results: The licensee was found to be in compliance with regulatory requirements in the 12 areas inspected.

8408030127 840730  
DR ADOCK 05000335  
Q PDR

ENCLOSURE CONTAINS  
SAFEGUARDS INFORMATION.  
UPON SEPARATION THIS  
PAGE IS DECONTROLLED.