

ENCLOSURE 2

U.S. NUCLEAR REGULATORY COMMISSION
REGION IV

Inspection Report: 50-445/95-23
50-446/95-23

Operating Licenses: NPF-87
NPF-89

Licensee: TU Electric
Skyway Tower
400 North Olive Street, L.B. 81
Dallas, Texas 75201

Facility Name: Comanche Peak Steam Electric Station, Units 1 & 2

Inspection At: Glen Rose, Texas

Inspection Conducted: October 2-5, 1995

Inspector: A. B. Earnest, Physical Security Specialist
Plant Support Branch

Approved:

Blaine Murray
Blaine Murray, Chief
Plant Support Branch

10-26-95
Date

Inspection Summary

Areas Inspected (Units 1 and 2): Routine, announced inspection of the licensee's physical security program. The areas inspected included records and reports, security audit program, package access control, vehicle access control, test and maintenance, protected area barriers, protected area detection aids, vital area barriers, and protection of safeguards information.

Results (Units 1 and 2):

- A good system of records and reports was maintained (Section 1.1).
- The 1995 audit of the security organization was an effective comprehensive review of the security program (Section 1.2).
- A very efficient program was maintained for searching hand carried packages (Section 1.3).
- A good program was established to provide control of vehicles inside the protected area (Section 1.4).
- An excellent test and maintenance program was maintained (Section 1.5).
- A good protected area barrier system was installed and maintained (Section 1.6).
- An excellent perimeter detection system was in place (Section 1.7).
- The vital area barriers were adequate to meet regulatory requirements (Section 1.8).
- A violation was identified involving the failure to protect safeguards information (Section 1.9).

Summary of Inspection Findings:

- Violation 445/9523-01; 446/9523-01 was opened (Section 1.9).

Attachment:

- Attachment - Persons Contacted and Exit Meeting