

The Light company

Houston Lighting & Power South Texas Project Electric Generating Station P. O. Box 289 Wadsworth, Texas 77483

March 16, 1992


ST-HL-AE-4035
File No.: T07.03
10CFR50

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

South Texas Project Electric Generating Station
Unit 2
Docket No. STN 50-499
Unit 2 Second Refueling Outage Inservice
Inspection Summary Report for Repairs and Replacements

Enclosed is the Unit 2 second refueling outage (2RE0.) Inservice Inspection Summary Report for Repairs and Replacements performed under the ASME Code, Section XI at the South Texas Project Electric Generating Station. This Summary Report includes the period from completion of the first refueling outage (December 11, 1990) to completion of the second refueling outage (December 18, 1991). In addition, an addendum to this Summary Report, for approximately 22 repairs and replacements will be submitted by April 17, 1992.

If you should have any questions on this matter, please contact Mr. A. W. Harrison at (512) 972-7298.



S. L. Rosen
Vice President,
Nuclear Engineering

SDP/amp

Attachments: Per Attached Index

200004

RREP\92072001.U2

A Subsidiary of Houston Industries Incorporated

9203200335 920316
PDR ADOCK 05000499
Q PDR

ACT 7

cc:

Regional Administrator, Region IV
Nuclear Regulatory Commission
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011

George Dick, Project Manager
U.S. Nuclear Regulatory Commission
Washington, DC 20555

J. I. Tapia
Senior Resident Inspector
c/o U. S. Nuclear Regulatory
Commission
P. O. Box 910
Bay City, TX 77414

J. R. Newman, Esquire
Newman & Holtzinger, P.C.
1615 L Street, N.W.
Washington, DC 20036

D. E. Ward/T. M. Puckett
Central Power and Light Company
P. O. Box 2121
Corpus Christi, TX 78403

J. C. Lanier/M. B. Lee
City of Austin
Electric Utility Department
P.O. Box 1088
Austin, TX 78767

K. J. Fiedler/M. T. Hardt
City Public Service Board
P. O. Box 1771
San Antonio, TX 78296

Rufus S. Scott
Associate General Counsel
Houston Lighting & Power Company
P. O. Box 61867
Houston, TX 77208

INPO
Records Center
1100 Circle 75 Parkway
Atlanta, GA 30339-3064

Dr. Joseph M. Hendrie
50 Bellport Lane
Bellport, NY 11713

D. K. Lacker
Bureau of Radiation Control
Texas Department of Health
1100 West 49th Street
Austin, TX 78756-3189

Revised 10/11/91

L4/NRC/

INDEX OF ATTACHMENTS

1. Cover Sheet
2. 2RE02 Inservice Inspection Summary Report for Repairs and Replacements