

Silverman, Mx<sup>10</sup>x<sub>3</sub>  
Henry Rx III  
Addtl. info Amend.  
no fee needed

HENRY R. (SILVERMAN, III, M.D.  
CARDIOLOGY AND INTERNAL MEDICINE  
3939 MONROE STREET.,  
SUITE 123  
TOLEDO, OHIO 43606  
TELEPHONE: 419-472-3232

June 1, 1984

Materials Licensing Branch  
Division of Fuel Cycle and Material Safety  
Office of Nuclear Material Safety and Safeguards  
U.S. Nuclear Regulatory Commission  
Region III  
799 Roosevelt Road  
Glen Ellyn, Illinois 60137

Re: Release of Area for Unrestricted Use for License  
No. 34-20317-01

030-18243

Gentlemen:

Pursuant to our license amendment No. 1, the nuclear medicine laboratory was moved to 3939 Monroe Street, Suite 123, Toledo, Ohio.

The former facility located at 3900 Sunforest court, Suite 214, has been closed.

In accordance with the guidelines established by the NRC, dated December 1975, "Guidelines for Decontamination of Facilities and Equipment Prior to Release for Unrestricted Use," we submit herein our final survey of the facility for your approval (refer to enclosure).

Following a thorough cleaning of the hot lab and scan room areas, wipe testing and survey meter monitorings were performed, as indicated on the enclosed diagram. Wipe tests were conducted on 100 cm<sup>2</sup> areas using absorbent paper moistened by alcohol. Counting of the wipe tests were conducted using a well counter having a 20% efficiency. Survey meter readings were conducted using a low range Ludlum survey meter. All radiation labels, symbols, etc., have been removed. Survey meter measurements were less than or equal to background, i.e. 0.01 mR/hr, for all areas monitored.

Please contact the undersigned if you have any questions regarding this matter.

Sincerely,

*HR Sil*  
Dr. Henry Silverman

RECEIVED BY LFMB  
Date: 6/8/84  
Log: 12/12/84  
By: [Signature]  
Orig. To: 12/12/84  
Action Compl: [Signature]

RECEIVED  
JUN 07 1984  
REGION III

8408200202 840626  
NMS LIC30  
34-20317-01 PDR

add info to  
EXEMPT JUN 7 1984  
3/29/84-ny

Control No. 76921

DR. HENRY SILVERMAN  
3939 Monroe Street  
Toledo, Ohio

Wipe Test Results


1. Less than background
2. Less than background
3. Less than background
4. Less than background
5. Less than background
6. Less than background
7. Less than background
8. Less than background
9. Less than background
10. Less than background
11. Less than background
12. Less than background
13. Less than background
14. Less than background
15. Less than background
16. Less than background
17. Less than background
18. Less than background
19. Less than background
20. Less than background
21. Less than background
22. Less than background
23. Less than background
24. Less than background
25. Less than background
26. Less than background

Background less than 0.01 mR/hr  
Background equivalent to 73 dpm

Survey Meter Results

- A. Less than 0.01 mR/hr
- B. Less than 0.01 mR/hr
- C. Less than 0.01 mR/hr
- D. Less than 0.01 mR/hr
- E. Less than 0.01 mR/hr
- F. Less than 0.01 mR/hr
- G. Less than 0.01 mR/hr
- H. Less than 0.01 mR/hr
- I. Less than 0.01 mR/hr
- J. Less than 0.01 mR/hr
- K. Less than 0.01 mR/hr
- L. Less than 0.01 mR/hr
- M. Less than 0.01 mR/hr
- N. Less than 0.01 mR/hr
- O. Less than 0.01 mR/hr
- P. Less than 0.01 mR/hr
- Q. Less than 0.01 mR/hr
- R. Less than 0.01 mR/hr
- S. Less than 0.01 mR/hr
- T. Less than 0.01 mR/hr
- U. Less than 0.01 mR/hr
- V. Less than 0.01 mR/hr
- W. Less than 0.01 mR/hr
- X. Less than 0.01 mR/hr
- Y. Less than 0.01 mR/hr
- Z. Less than 0.01 mR/hr

sink, storage area



\* Letters indicate locations of survey meter measurements

\* Numbers indicate locations of wipe tests