



GFU Nuclear Corporation
Post Office Box 480
Route 441 South
Middletown, Pennsylvania 17057-0191
717 944-7621
TELEX 84-2386
Writer's Direct Dial Number:

August 31, 1984
5211-84-2224


Office of Nuclear Reactor Regulation
Attn: John F. Stolz, Chief
Operating Reactors Branch No. 4
U. S. Nuclear Regulatory Commission
Washington, D.C. 20555

Dear Sir:

Three Mile Island Nuclear Station, Unit 1 (TMI-1)
Operating License No. DPR-50
Docket No. 50-289
Post Accident Sampling (NUREG 0737, Item II.B.3)

This is in response to your letter of March 22, 1984, which included the Safety Evaluation by NRR of the TMI-1 Post Accident Sampling System compliance with NUREG 0737, Item II.B.3. Enclosed is TMINS Unit 1 Emergency Plan Implementing Procedure 1004.33, Rev. 7, which includes the methodology for estimating the extent of core damage following an accident taking into consideration other physical parameters in addition to fission product activities.

Sincerely,


H. D. Hukill
Director, TMI-1

HDH:MRK:vjf

Enclosure

cc: J. Van Vliet, NRC Project Manager
R. Conte, NRC Resident Inspector
Dr. T. E. Murley, NRC Region I, Regional Administrator

840910J081 840831
PDR ADOCK 05000289
F PDR

A045
11