#### OPERATING DATA REPORT

DOCKET NO. 50-333

DATE Sept. 1984

COMPLETED BY J. Cook
TELEPHONE (315) 342-3840

| OPERATING STATUS   |                         |                        |                   |  |
|--|-------------------------|------------------------|-------------------|--|
| 1. Unit Name: FitzPatrick  |                         | Notes                  |                   |  |
| 2. Reporting Period: 840801 - 8408   | 31                      |                        |                   |  |
| 3. Licensed Thermal Power (MWt):   |                         |                        |                   |  |
| 4. Nameplate Rating (Gross MWe):   |                         |                        |                   |  |
| 5. Design Electrical Rating (Net MWe):   | 821                     |                        |                   |  |
| 6. Maximum Dependable Capacity (Gross MWe):  | 830                     |                        |                   |  |
| 7. Maximum Dependable Capacity (Net MWe):  | 810                     |                        |                   |  |
| 8. If Changes Occur in Capacity Ratings (Items Nu  | umber 3 Through 7) Sin  | ce Last Report Cive I  | Dancone:          |  |
| None   |                         | ce bast report, dire i | ceasons.          |  |
| 9. Power Level To Which Restricted, If Any (Net !  | MWe): None              |                        |                   |  |
| 10. Reasons For Restrictions, If Any:  |                         |                        |                   |  |
|  |                         |                        | ***               |  |
|  | This Month              | Yrto-Date              | Cumulative        |  |
| 11. Hours In Reporting Period  | 744                     | 5855                   | 79752             |  |
| 2. Number Of Hours Reactor Was Critical  | 637.4                   | 5364                   | 57892.8           |  |
| 3. Reactor Reserve Shutdown Hours  | 0                       | 0                      | 0                 |  |
| 14. Hours Generator On-Line  | 615.4                   | 5234.8                 | 56434.4           |  |
| 5. Unit Reserve Shutdown Hours   | 0                       | 0                      | 0                 |  |
| 6. Gross Thermal Energy Generated (MWH)  | 1354488                 | 12013608               | 119750194         |  |
| 7. Gross Electrical Energy Generated (MWH)   | 436680                  | 4000969                | 41220150          |  |
| 8. Net Electrical Energy Generated (MWH)   | 422335                  | 3873435                | 39372075          |  |
| 9. Unit Service Factor   | 82.7%                   | 89.4%                  | 79.8%             |  |
| 0. Unit Availability Factor  | 82.7%                   | 89.4%                  | 70.8%             |  |
| 1. Unit Capacity Factor (Using MDC Net)  | 70.1%                   | 81.7%                  | 64.4%             |  |
| 2. Unit Capacity Factor (Using DER Net)  | 69.1%                   | 80.6%                  | 69.1%             |  |
| 3. Unit Forced Outage Rate   | 17.3%                   | 5.0%                   | 13.8%             |  |
| 4. Shutdowns Scheduled Over Next 6 Months (Typ   | e, Date, and Duration o | f Each):               |                   |  |
| Maintenance outage scheduled   | for September           | 14. 1984 to            | last              |  |
| approximately 30 days.   |                         |                        |                   |  |
| approximately 30 days.   |                         | : 14, 1984 to          | last              |  |
| <ol> <li>If Shut Down At End Of Report Period, Estimat</li> <li>Units In Test Status (Prior to Commercial Opera</li> </ol> | tion):                  | Forecast               | Achieved          |  |
|  |                         |                        |                   |  |
| INITIAL CRITICALITY  |                         |                        | The second second |  |
| INITIAL ELECTRICITY  |                         |                        |                   |  |
| COMMERCIAL OPERATION   |                         |                        |                   |  |
| 8409200494 840831  |                         |                        |                   |  |
| PDR ADOCK 05000333   |                         |                        | IE 24             |  |

#### AVERAGE DAILY UNIT POWER LEVEL

DOCKET NO. 50-333

UNIT FitzPatrick

DATE Sept. 1984

COMPLETED BY J.Cook

TELEPHONE (315) 342-3840

| AVERAGE DAILY POWER LEVEL (MWe-Net) | DAY | AVERAGE DAILY POWER LEVEL (MWe-Net) |
|-------------------------------------|-----|-------------------------------------|
| 755                                 | 17  | 628                                 |
| 752                                 | 18  | 607                                 |
| 741                                 | 19  | 693                                 |
| 703                                 | 20  | 731                                 |
| 515                                 | 21  | 753                                 |
| 17                                  |     | 750                                 |
| 0                                   | 22  | 753                                 |
| 0                                   | 23  | 749                                 |
| 0                                   | 24  | 767                                 |
| 0                                   | 25  | 743                                 |
| 125                                 | 26  | 747                                 |
| 437                                 | 27  | 753                                 |
| 619                                 | 28  | 726                                 |
| 716                                 | 29  | 730                                 |
| 677                                 | 30  | 746                                 |
| 665                                 | 31  | 740                                 |

SUMMARY: The Fitzpatrick Plant operated at slightly reduced power during this reporting period due to high lake temperatures causing a low condenser vacuum. On 840805 the plant was taken off line to repair a RECIRC pump seal and returned to service on 840811.

#### UNIT SHUTDOWNS AND POWER REDUCTIONS

REPORT MONTH August 1984

50-333 DOCKET NO. FitzPatrick UNIT NAME Sept. 1984 DATE COMPLETED BY J. Cook TELEPHONE (315) 342-3840

| No. | Date   | Type1 | Duration<br>(Hours) | Reason | Method of<br>Shutting<br>Down Reactor <sup>3</sup> | Licensee<br>Event<br>Report # | System<br>Code4 | Component<br>Code5 | Cause & Corrective Action to Prevent Recurrence   |
|-----|--------|-------|---------------------|--------|--|-------------------------------|-----------------|--------------------|---|
| 11  | 840805 | F     | 128.6               | A      | 2  | N/A                           | AD              | P                  | Shutdown to investigate drywell leakage 25gpm which was caused by a Recirc nump seal failure. Seal was replaced and unit returned to service. |

F: Forced S: Scheduled

Reason:

A-Equipment Failure (Explain)

B-Maintenance of Test

C-Refueling

D-Regulatory Restriction

E-Operator Training & License Examination

F-Administrative

G-Operational Error (Explain)

II-Other (Explain)

3

Method: 1-Manual

2-Manual Scram.

3-Automatic Scram.

4-Other (Explain)

Exhibit G - Instructions for Preparation of Data Entry Sheets for Licensee Event Report (LER) File (NUREG-0161)

Exhibit 1 - Same Source

### NARRATIVE SUMMARY OF OPERATING EXPERIENCE

#### AUGUST 1984

The FitzPatrick plant operated at slightly reduced power for this period due to low condenser vacuum caused by high lake temperatures. On 840805 the unit was taken off-line to investigate drywell leakage less than 5gpm. The source of leakage was found to be a failed recirculation pump seal which was repaired and the plant returned to service on 840811.

At the end of the reporting period the FitzPatrick plant is operating at approximately 746  $\mathrm{MW}_{\mathrm{e}}$  .

## JAMES A. FITZPATRICK NUCLEAR POWER PLANT

## SAFETY RELATED ELECTRICAL & MECHANICAL MAINTENANCE SUMMARY

| DATE | SYSTEM | WORK REQUEST # COMPONENT #                           | HOW DETECTED | CAUSE OF MALFUNCTION         | ACTION TAKEN TO PRECLUDE RECURRENCE          | REPA<br>TIME<br>HOUR |
|------|--------|--|--------------|------------------------------|--|----------------------|
| 8/3  | 13     | 33540<br>RCI-750                                     | Visual       | Corroded packing follower    | Cleaned packing follower.<br>Re-packed valve | 8                    |
| 8/9  | 23     | 33562<br>1"-WD-<br>902-22                            | Visual       | Eroded pipe                  | Replaced section of pipe                     | 60                   |
| 7/13 | 71     | 33593<br>13M0V-15<br>23M0V15<br>12M0V15<br>02M0V-53B | OPS          | Suspected packing<br>leakage | Backseated                                   | 4                    |
| 8/10 | 02-2   | 25038<br>P-1A  | OPS          | Overheated Seal              | Replaced seal                                | 204                  |
| 8/15 | 66     | 15039<br>HV-3B                                       | Visual       | Missing Unistrut<br>support  | Replaced Unistrut                            | 1                    |
|      |        |  |              |                              |  |                      |
|      |        |  |              |                              |  |                      |

## JAMES A. FITZPATRICK NUCLEAR POWER PLANT

## SAFETY RELATED ELECTRICAL & MECHANICAL MAINTENANCE SUMMARY

| DATE | SYSTEM | WORK REQUEST # COMPONENT #          | HOW DETECTED      | CAUSE OF MALFUNCTION   | ACTION TAKEN TO PRECLUDE RECURRENCE                              | REPA<br>TIME<br>HOUR |
|------|--------|-------------------------------------|-------------------|--|--|----------------------|
| 8/14 | 46     | 23921<br>P-2B<br>Circuit<br>Breaker | Maint.<br>Testing | Adjusted using un-<br>calibrated test<br>equip. & unstable<br>trip devices | Replaced trip devices,<br>adjusted using calibrated<br>equipment | 60                   |
| 8/20 | 70     | 22870<br>TCV-121A                   | Visual            | Damaged sealtite   | Repaired sealtite  | 8                    |
| 8/18 | 10     | 31542<br>MOV-66A                    | OPS               | Dirt on contactor<br>caused sticking                                       | Cleaned contactor.<br>Stroked valve                              | 4                    |
| 8/22 | 66     | 29617<br>AOV-1018                   | OPS               | Age  | Replaced split air hose  | 10                   |
| 8/24 | 71     | 22829<br>BAT 3A                     | S.T.              | Low I.C.V<br>sulfation   | Jumpered cell #118   | 12                   |
|      |        |                                     |                   |  |  |                      |
|      |        |                                     |                   |  |  |                      |
|      |        |                                     |                   |  |  |                      |

## NEW YORK POWER AUTHORITY—JAMES A. FITZPATRICK NUCLEAR POWER PLANT

# MAINTENANCE SUMMARY August 1984

| DATE   | SYSTEM | WORK REQUEST NO. COMPONENT NO. | HOW<br>DETECTED | CAUSE OF MALFUNCTION                | RESULTS OF MALFUNCTION             | ACTION TAKEN<br>TO PRECLUDE<br>RECURRENCE | REPAIR<br>TIME<br>HOURS |
|--------|--------|--------------------------------|-----------------|-------------------------------------|------------------------------------|---|-------------------------|
| 840831 | 02-3   | 029173<br>TU-278c              | OPS             | Failed Power<br>Supply in ATTS      | RX Pres.Indicates                  | Renaired PS                               | 30                      |
| 840808 | 02-3   | 029169<br>LITS-79              | I&C             | Age, Use                            | Leaky Instrument<br>Manifold VLV.  | Replaced<br>Manifold                      | 8                       |
| 840809 | 03     | 033425<br>RD SEL SW            | OPS             | Age, Use                            | RD-30-23 Inter.<br>Rd-22-31 BAD    | Renlaced<br>Switches                      | 12                      |
| 840808 | 03     | 031479<br>RD SEL SW            | OPS             | Age, Use                            | RD-38-11 Switch<br>Bad             | Replaced Switch                           | 4                       |
| 840831 | 06     | 033410<br>PI-90C               | OPS             | Defective Meter<br>(GE/MAC 180)     | Indicator Reads<br>Higher than A   | Replaced Meter/<br>Calibrated             | 28                      |
| 840820 | 07     | 033469<br>NM-41C,G             | OPS             | Internal Power<br>Supply Drift      | IRMC,G Read Low<br>on ST-5M        | Adjusted Per<br>IMP-7.3                   | 3                       |
| 840817 | 07     | 033445<br>SRM A PER.           | OPS             | Defective Meter<br>(GE/MAC 180)     | Remote Period<br>Meter Reads HI    | Replaced Meter/<br>Calibrated             | 20                      |
| 840314 | 07     | 033493<br>RBM-B                | OPS             | Open Contact in<br>RSCS PWR. Switch | RBM. B Doesn't<br>see Periph. Rods | Operated Switch<br>Several Times          | 4                       |
| 840730 | 07     | 033603<br>NM-131-4             | OPS             | Traces Don't<br>Come Out Right      | X-Y Plotter Needs<br>Alignment     | Aligned All<br>Machines                   | 24                      |
| 840724 | 10     | 033402<br>LS-101               | OPS             | Shorted Circuit<br>Board Inside     | No Indication<br>of Power On       | Replaced Board                            | 6                       |
| 840807 | 11     | 033463<br>AM-SBLC-A            | OPS             | Blown Bulb In<br>Meter Relay        | Meter is Giving<br>Loss of Cont.   | Replaced Bulb                             | 9                       |
| 840821 | 16     | 033522<br>X-104                | OPS             | Minute Slow<br>Leak                 | Electrical Pene-<br>tration Low    | Recharged Pene-<br>tration                | 2                       |

# NEW YORK POWER AUTHORITY—JAMES A. FITZPATRICK NUCLEAR POWER PLANT MAINTENANCE SUMMARY August 1984

| DATE   | SYSTEM | WORK REQUEST NO. COMPONENT NO. | HOW   | CAUSE OF MALFUNCTION              | RESULTS OF MALFUNCTION              | ACTION TAKEN<br>TO PRECLUDE<br>RECURRENCE | REPAIR<br>TIME<br>HOURS |
|--------|--------|--------------------------------|-------|-----------------------------------|-------------------------------------|---|-------------------------|
| 840831 | 17     | 034959<br>RR-152               | OPS   | Red Pen Broke<br>At Ret. Screw    | Recorder Didn't<br>Pass ST-11       | Replaced Pen/<br>Calibrated               | 4                       |
| 840817 | 17     | 033509<br>RIS-458A,B           | OPS   | 458A Out of<br>Adjustment         | 458A, B Don't<br>Match              | Adjusted Per<br>ISP-26                    | 12                      |
| 840814 | 17     | 033449<br>RIS-459              | OPS   | Defective Amp.<br>On Recorder     | Recorder and Met<br>Don't Match     | er Replaced Amp/<br>Calibrated            | 14                      |
| 840810 | 17     | 023039<br>RM-251C              | RES . | Source Check By<br>Rad Protection | Suspected<br>Calibration<br>Problem | Calibrated Per<br>ISP-64-1,2              | 3                       |
| 840730 | 17     | 031095<br>RM-251A              | I&C   | Relay K-17 in .<br>Trip Circ. Def | Unit Doesn't<br>Alarm Properly      | Replaced Relay                            | 2                       |
| 840801 | 20     | 033644<br>AOV-95               | OPS   | LT-120A OutPut<br>Stuck at 3.25V  | Valve Won't Open<br>On Hi Level     | Use Signal From<br>LT-120B to VLV         | 28                      |
| 840828 | 27     | 033922<br>PCV-122A             | OPS   | Dirty Air Nozzle<br>On Controller | Valve Not Main-<br>taining TK Pres  | Cleaned PC-122A/<br>Calibrated            | 16                      |
| 840802 | 70     | 029612<br>TCV-121A             | OPS   | Valve Stroke Not<br>Set Right     | Valve Won't re-<br>spond to signal  | Seated and Stroker<br>Valve               | d 8                     |
| 840824 | 72     | 031643<br>TCV-204A&B           | OPS   | A No Air Pres/B<br>Broke Gauges   | 204A Stuck Shut<br>204B Leaks Air   | A Set Pres/ B<br>Replaced Gauges          | 12                      |
| 840820 | 76     | 033499<br>Relay 62 M           | OPS   | Drift                             | Timer Times Out<br>Too Long         | Adjusted Timer                            | 14                      |
| 840809 | 76     | 033471<br>Zone 2S              | OPS   | DXT Board/Relays<br>R10A,B Bad    | Spurious Alarms                     | Replaced<br>Defective<br>Components       | 20                      |

James A. FitzPatrick Nuclear Power Plant P.O. Box 41 Lycoming, New York 13093 315 342.3840

NewYork Power Authority

September 10, 1984 JAFP 84-0863

Director, Office of Inspection and Enforcement U.S. Nuclear Regulatory Commission Washington, D.C. 20555

ATTENTION:

DOCUMENT CONTROL DESK

REFERENCE:

DOCKET NO. 50-333

Dear Sir:

The Operating Status Report for the month of August 1984 is enclosed. The refueling information remains the same as previously submitted.

If there are any questions concerning this report, contact John Cook at (315) 342-3840, Ext. 439.

Very truly yours,

CORBIN A. MCNEILL, JR.

CAM: JPC: tls

cc: Internal Distribution

Enclosures

1E24

Corbin A. McNeill, Jr.

Resident Manager