



Northeast
Utilities System

107 Selden Street, Berlin, CT 06037

Northeast Utilities Service Company
P.O. Box 270
Hartford, CT 06141-0270
(203) 665-5000

September 29, 1995

Docket No. 50-423
B15375

Re: ASME Section XI
GL 90-05

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555

Millstone Nuclear Power Station, Unit No. 3
Request for Relief from ASME Code Section XI Requirements

In a letter dated May 23, 1994,⁽¹⁾ Northeast Nuclear Energy Company (NNECO) submitted, for NRC Staff review, a request for relief from ASME Code Section XI requirements for an interim repair in service water system piping line 3SWP-030-344-3 at Millstone Unit No. 3. Specifically, the leak is located at 12 o'clock on a 3/4" test connection approximately 1 1/2" from the 30" header connection on the B train of the component coolant water heat exchanger service water return piping. The piping involved in the above-mentioned relief request has been repaired in accordance with ASME Code Section XI requirements, and, therefore, the relief request is hereby withdrawn.

NNECO appreciates any effort which may have been initiated by the Staff. Please contact Mr. R. G. Joshi at (203) 440-2080 if you have any questions.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY

FOR: J. F. Opeka
Executive Vice President

BY:
D. B. Miller, Jr.
Senior Vice President - Millstone

cc: See Page 2

(1) J. F. Opeka letter to U.S. Nuclear Regulatory Commission, "Relief Request from ASME Code Section XI Requirements," dated May 23, 1994.

A047/10

U.S. Nuclear Regulatory Commission
B15375/Page 2
September 29, 1995

cc: T. T. Martin, Region I Administrator
V. L. Rooney, NRC Project Manager, Millstone Unit No. 3
P. D. Swetland, Senior Resident Inspector, Millstone Unit Nos.
1, 2, and 3