

U. S. NUCLEAR REGULATORY COMMISSION

REGION III

Report No. 50-341/84-34(DRSS)

Docket No. 50-341

License No. CPPR-87

Safeguards Group IV

Licensee: Detroit Edison Company
2000 Second Avenue
Detroit, MI 48226

Facility Name: Enrico Fermi Atomic Power Plant, Unit 2

Inspection At: Plant Site and Offsite Weapons Firing Range

Inspection Conducted: August 20-24 and 27-29, 1984

Date of Last Physical Security Inspection: July 11-13, 1984

Type of Inspection: Announced, Pre-Operational Physical Security

Inspectors: *Terry J. Madeda*
T. J. Madeda
Physical Security Inspector

9/19/84
Date

Bernard Stapleton
J. L. Belanger
for Physical Security Inspector

9-19-84
Date

Bernard Stapleton
B. W. Stapleton
Physical Security Inspector

9-19-84
Date

Approved By: *Bernard Stapleton*
J. R. Creed, Chief
for Physical Security Section

9-19-84
Date

Inspection Summary

Inspection on August 20-24 and 27-29, 1984 (Report No. 50-341/84-34[DRSS])
Areas Inspected: Included a review of the status of implementation; installation; operability of the security program and the preoperational testing program for security related equipment. Specifically, the inspection covered: Security Plan and Implementing Procedures; Security Organization - Management, Personnel and Response; Security Program Audit; Records and Reports; Testing and Maintenance, Locks, Keys, and Combinations; Physical Barriers - Protected and Vital Areas; Security System Power Supply; Lighting; Assessment Aids; Access Control - Personnel, Packages, and Vehicles; Detection Aids - Protected and Vital Areas; Alarm Stations; Communications; and General Requirements T&Q

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled

8409280231 840925
PDR ADOCK 05000341
PDR
G

Plan. This inspection involved 91 direct inspector-hours by three NRC inspectors. The inspection was begun during the day shift.

Results: Based on the preoperational inspection, the inspectors determined the status of the security program and identified areas that must be completed prior to fuel load. No items of noncompliance were identified.

(DETAILS: UNCLASSIFIED SAFEGUARDS INFORMATION)

Enclosure contains
SAFEGUARDS INFORMATION
Upon separation this
page is Decontrolled