UNITED STATES



## NUCLEAR REGULATORY COMMISSION

REGION IV

611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011 8064

AUG - 7 1992

Docket Nos. 50-445 50-446 License No. NPF-87 Construction Permit No. CPPR-127

TU Electric
ATTN: W. J. Cahill, Jr., Group Vice President
Nuclear Engineering and Operations
Skyway Tower
400 North Olive Street, L.B. 81
Dallas, Texas 75201

Gentlemen:

SUBJECT: NRC INSPECTION REPORT NOS. 50-445/92-23; 50-446/92-23 (NOTICE OF VIOLATION)

This refers to the inspection conducted by Mr. W. M. McNeill of this office on June 22-25, 1992. The inspection included a review of activities authorized for your Comanche Peak Steam Electric Station, Units 1 and 2. At the conclusion of the inspection, the findings were discussed with you and those members of your staff identified in the enclosed report.

Areas examined during the inspection are identified in the report and included quality assurance administration and control of measuring and test equipment. Within these areas, the inspection consisted of selective examination of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are documented in the enclosed report.

Based on the results of this inspection, certain of your activities appeared to be in violation of NRC requirements, as specified in the enclosed Notice of Violation (Notice). This violation represents a failure to provide traceability and administrative controls over vendor supplied test equipment. Although this violation is classified at Severity Level V, you are requested to respond since the concern was identified by the NRC inspector and corrective actions were not in place at the end of this inspection.

You are required to respond to this letter and should follow the instructions specified in the enclosed Notice when preparing your response. In your response, you should document the specific actions taken and any additional actions you plan to prevent recurrence. After reviewing your response to the Notice, including your proposed corrective actions and the results of future inspections the NRC will determine whether further NRC enforcement action is necessary to ensure compliance with NRC regulatory requirements.

9208130221 920807 PDR ADDCK 05000445 Fill

TU Electric -2-

In accordance with 10 CFR Part 2.790 of the NRC's "Rules of Practice," a copy of this letter and its enclosures will be placed in the NRC Public Document Room.

The response directed by this letter and the enclosed Notice are not subject to the clearance procedures of the Office of Management and Budget as required by the Paperwork Reduction Act of 1980, Pub. L. No. 96.511.

Should you have any questions concerning this inspection, we will be pleased to discuss them with you.

Sincerely,

A. Bill Beach, Director Division of Reactor Projects

Enclosures:

 Appendix A - Notice of Violation
 Appendix B - NRC Inspection Report 50-445/92-23 w/Attachment 50-446/92-23 w/Attachment

cc w/enclosures: TU Electric ATTN: Roger D. Walker, Manager Nuclear Licensing Skyway Tower 400 North Olive Street, L.B. 81 Dallas, Texas 75201

Juanita Ellis President - CASE 1426 South Polk Street Dallas, Texas 75224

GDS Associates, Inc. Suite 720 1850 Parkway Place Marietta, Georgia 30067-8237

TU Electric Bethesda Licensing 3 Metro Center, Suite 610 Bethesda, Maryland 20814 Jorden, Schulte, and Burchette ATTN: William A. Burchette, Esq. Counsel for Tex-La Electric Cooperative of Texas 1025 Thomas Jefferson St., N.W. Washington, D.C. 20007

Newman & Holtzinger, P.C. ATTN: Jack R. Newman, Esq. 1615 L. Street, N.W. Suite 1000 Washington, D.C. 20036

Texas Department of Labor & Standards ATTN: G. R. Bynog, Program Manager/ Chief Inspector Boiler Division P.O. Box 12157, Capitol Station Austin, Texas 78711

Honorable Dale McPherson County Judge P.O. Box 851 Glen Rose, Texas 76043

Texas Radiation Control Program Director 1100 West 49th Street Austin, Texas 78756

Owen L. Thero, President Quality Technology Company Lakeview Mobile Home Park, Lot 35 4793 E. Loop S22 South Fort Worth, Texas 76119 B. McNeill

NRC Inspection Report 50-445/92-23; 50-446/92-23

bcc to DMB (IEO1) - DRS

bcc distrib. by RIV:

James L. Milhoan DRP Lisa Shea, RM/ALF, MS: MNBB 4503 DRSS-FIPS Project Engineer (DRP/B) DRS 1. Barnes Resident Inspector (2)
Section Chief (DRP/B)
MIS System
RSTS Operator
RIV File
Chief, Technical Support Section

		8/1/2		
RIV:RI:MQPS*	C:MQPS*	DORS /	D:02	
BMcNeill/cjg	IBarnes	SOCOTTing	ABBeach	
/ /92	/ /92	12/5/82	8/7/92	

<sup>\*</sup>previously concurred