


REVISED

FIELD INSPECTION REPORT

3. RECORD CONTROL  
CONTROL NO. C-63  
FILE NO. JM-1-4512

1. PROJECT NO. 9931 2. DATE 10/26/76 PAGE \_\_\_\_\_ OF \_\_\_\_\_

4. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED  
THE FOLLOWING O.C.T. INSPECTION PLANS: C109 W1-4  
C192 W1-9 C201 W1-7 C201 W1-10



5. LOCATION REACTOR #2 FLV 253' AREA 13-17

6. TYPE OF INSPECTION VISUAL & DIMENSIONAL

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1-1 72 R1-73 R2-74  
C91-1 12-26-76 WQ 2/0 CG3-1 PART 1-5 2/4 FN/2 C109 W1-4  
C192 W1-9 C201 W1-7 C201 W1-10  
NCR 1980

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY  UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY \_\_\_\_\_

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED. ALSO SEE  
DCG1-1 REPORT NOS. C-63-3 DATED 10-27-76 AND  
C-63-14 DATED 11-2-76. NO DISIN  
ALSO FOR RE-INSPECTION - SEE REPORT C-63-22 DATED 4-5-77  
NO DISIN 7-2

Distribution:  
White - CC Files  
Canary - Originator

*K. B. ...*

11. ENGINEER *[Signature]*