

REC-115

FIELD INSPECTION REPORT

U. RECORD CONTROL  
CONTROL NO. C-63-7  
FILE NO. 7-28-77

1. PROJECT NO S-031 2. DATE 10/27/76 PAGE      OF     

4. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING D.C.T. INSPECTION PLANS. C192 W1-4 C199 W1-4 C201 W1-7 C201 W1-9 C201 W1-10

5. LOCATION REACTOR #2 ELV 253 AREA 17 19-10

6. TYPE OF INSPECTION VISUAL + DIMENSIONAL

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1-172 R-1-77 R 2-74 C63-1 APP 1-2 FA 2 W0 2/0 C91/16 10-27-76 2 C192 W1-4 C199 W1-4 C201 W1-7 C201 W1-9 C201 W1-10 NCR 1990

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY  UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY     

NOTE: FOR PREVIOUS INSPECTIONS AND RE-INSPECTIONS ACCOMPLISHED ALSO SEE DCGI-1 REPORT NOS. C-63-7 DATED 10-26-76 AND C-63-14 DATED 11-2-76. MODIFIED ALSO FOR RE-INSPECTION. SEE REPORT C-63-22 DATED 4-5-77 7-28-77 7-28-77

Distribute on:  
White - CC Files  
Canary - Originator

*[Signature]*

11. ENGINEER *[Signature]*