

RECEIVED


FIELD INSPECTION REPORT

3 RECORD CONTROL
CONTROL NO. C-63-
FILE NO. 1K-1-C-1

1. PROJECT NO. 9031 2. DATE 10/25/76 PAGE OF

4. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING O.C.T. INSPECTION PLANS C199 W1-17 C195 W1-17

5. LOCATION REACTOR #2 ELV 217 AREA 17, 15



6. TYPE OF INSPECTION VISUAL + DIMENSIONAL

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D.1-1.22 P1.23 P2.24
CGI/WG 2/0 C63.1 ADOT 1-7 SA12
C199 W1-13 C195 W1-17 C199 W1-17
NCR #1980

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY NCR 1998 WAS GENERATED DUE TO UNACCEPTABLE WELDS COVERED ON O.C.T.R. C195 W1.

NOTE - FOR RE-INSPECTIONS ACCOMPLISHED - ALSO SEE OLG1-1 REPORT # C-63-22 DATED 4-5-77. CHADWICK 7-25

Distribution:
White - GC Files
Canary - Originator

K.B. Iler

11. ENGINEER J. J. [Signature]