

RE-112

FIELD INSPECTION REPORT

RECORD CONTROL  
CONTROL NO. C-63-1  
FILE NO. 22-11-49

1. PROJECT NO. 5031 2. DATE 10/29/76 PAGE 1 OF 1

4. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED  
THE FOLLOWING D.C.T. INSPECTION PLANS. C 197 W 1-10  
C 197 W 1-9A C 197 W 1-11

5. LOCATION REACTOR #1 SW 217 229A 11 15 + 16

6. TYPE OF INSPECTION VISUAL + DIMENSIONAL



7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AMS D1-1.72 R-1.72 R2.74  
C 9112 W 9 210 C 63-1 PART 1-4 FA2  
C 197 W 1-10 C 197 W 1-9A C 197 W 1-11 NCR 1950

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY  UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED ALSO  
SEE REPORT # 063-22 DATED 4-5-77 MODIFIED 7-28

Distribution:  
White - CC Files  
Canary - Originator

*L. B. Biles*

11. ENGINEER *[Signature]*