

REVISIONS


FIELD INSPECTION REPORT

3 RECORD CONTROL
CONTROL NO. C-63
FILE NO. 101127

1. PROJECT NO. 5031 2. DATE 10/29/76 PAGE OF

4. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING QC INSPECTION PLANS:
C195 W1-11 C194 W1-16 C194 W1-17 C194 W1-19

5. LOCATION REACTOR #2 ELV 201 AREA U-15-16



6. TYPE OF INSPECTION VISUAL + DIMENSIONAL

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1.1-72 RI. 73 P2. 74
C91/G W0-2/0 C63/1 PART 1-5 FA#2 C195 W1-11
C194 W1-16 C194 W1-17 C194 W1-19 NCR #1980

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY NCR-2000 WAS GENERATED DU TO UNACCEPTABLE WELDS COVERED ON O.G.P. C195 W1-11

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED ALSO SEE OGGI-1 REPORT - C63-22 DATED 4-5-77
7-28-77

Distribution:
White - CC Files
Canary - Originator

K. B. BILLY 11-1-76

11. ENGINEER [Signature]