



FIELD INSPECTION REPORT

3. RECORD CONTROL  
CONTROL NO. C-63-12  
FILE NO. EP-44-3-12


1. PROJECT NO. 9031 2. DATE 11/1/76 PAGE \_\_\_\_\_ OF \_\_\_\_\_

4. ITEM INSPECTED PARTIAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING Q.I.T. INSPECTION PLANS.

C201 W1-5 C204 W1-2

5. LOCATION REACTOR #2 ELV 253 + 2.93 AREA 13 + 14

6. TYPE OF INSPECTION VISUAL & DIMENSIONAL



7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1-1-72 REV 1-73 REV 2-74  
C91 REV 6 WQ 2/0 C63 REV 1 ADDIT 1-5, FA'2  
C201 W1-5 C204 W1-2 NCR 1980

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY  UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY \_\_\_\_\_  
B411270224 B40507  
PDR ADCK 05000352  
G PDR

NOTE: FOR RE INSPECTIONS ACCOMPLISHED ALSO SEE OGGI-1 REPORT NOS. C-63-28 DATED 7-1-77 AND C-63-29 DATED 7-1-77. WORKMAN 7-28-77 ALSO SEE REPORT C-63-22 DATED 4-5-77

Distributor  
White - QC Files  
Cantley - Originals

W. Bishop 11-1-76

11. ENGINEER *[Signature]*