



FIELD INSPECTION REPORT

3. RECORD CONTROL  
CONTROL NO. C-63-13  
FILE NO. EPC-41-43-12

1. PROJECT NO. 8031 2. DATE 10/20/76 PAGE \_\_\_\_\_ OF \_\_\_\_\_

4. ITEM INSPECTED PARTIAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING O.C.T. INSPECTION PLANS.  
C195 W1-6 C194 W1-5 C193 W1-10

5. LOCATION REACTOR #2 ELV -01 AREA 11, 12 + 13

6. TYPE OF INSPECTION VISUAL + DIMENSIONAL



7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION. AW5 01-1-73 REV 1-73  
REV 2-74 C91RFLC WQ 7/0 C63 REV1 ADDIT 1-5 FA  
C195 W1-6 C194 W1-5 C193 W1-10 NCR 1980

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY  UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY \_\_\_\_\_  
8411270229 840507  
PDR ADOCK 05000352  
G PDR

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED ALSO SEE OCGI-1 REPORT NOS. C-63-24 DATED 7-5-77 AND C-63-27 DATED 7-5-77. 7-28-77  
ALSO RE-INSPECTION REPORT C-63-26 DATED 7-5-77 7-28-77  
ALSO RE-INSPECTION REPORT C-63-22 DATED 4-2-77 7-28-77

Distributor  
White - GC Form  
Cahoon - Original

L.L. B... 10-29-76

11. ENGINEER [Signature]