



FIELD INSPECTION REPORT


3. RECORD CONTROL
CONTROL NO. C-63-14
FILE NO. FCC-1-663-11

1. PROJECT NO. 8031 2. DATE 11/2/76 PAGE OF

4. ITEM INSPECTED TOTAL RE. INSPECTION OF WELD ACCOMPLISHED ON THE FOLLOWING O.C.T. INSPECTION PLAN

C 201 W 1-10

5. LOCATION REACTOR #2 ELV 2.53 AREA 17



6. TYPE OF INSPECTION VISUAL + DIMENSIONAL

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWS D1-1.73 REV 1-73
REV 2-74 CGI REV G W Q 2/0 CG3 REV I ADOT 1-C, FR #2
C 201 W 1-10 NCR 1950

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY

8411270232 840507
PDR ADOCK 05000352
G PDR

NOTE: FOR PREVIOUS INSPECTIONS ACCOMPLISH ALSO SEE OCGI-1 REPORT NOS. C63-7 DATED 10-26-76 AND C-63-8 DATED 10-27-76. WORKING 7-28-77 ALSO F.R. RE-INSPECTIONS - 540 REPORT # C-63-22 DATED 4-5-77 WORKING 7-28-77

Distribution
White - CS File
Green - Original

K. B. B. 11-2-76

11. ENGINEER [Signature]