




FIELD INSPECTION REPORT

3. RECORD CONTROL
CONTROL NO. C-63-15
FILE NO. 2000000000

1. PROJECT NO. S031 2. DATE 11/17/76 PAGE _____ OF _____

4. ITEM INSPECTED TOTAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING Q.C.T INSPECTION OPENING

C 199 W1-14



5. LOCATION REACTOR #2 SLV 217 AREA 13+17

6. TYPE OF INSPECTION VISUAL + DIMENSIONAL

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AWIS D1-1-72 REV 2-73
REV 2-74 2916 W O 210 CG3 REV1 ADIT 1-5, FP#2
C 199 W1-14 NCR 1990

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY _____

NOTE - FOR RE INSPECTIONS ACCOMPLISHED SEE ALSO OCGI-1 REPORT # C-63-22 DATED 4-5-77 7-28-77

8411270240 840507
PDR ADOCK 05000352
PDR

Distribution
Who - GC Files
Copy - Original

KL Bilby 11-1-76

11. ENGINEER [Signature]