



FIELD INSPECTION REPORT

3. RECORD CONTROL
 CONTROL NO C-63-16
 FILE NO IPC-14-23-4


1. PROJECT NO. 5031 2. DATE 11/1/76 PAGE _____ OF _____

4. ITEM INSPECTED PARTIAL RE-INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING O&I INSPECTION PLANS

C 41A 115 WI-1 C 197 WI-6 C 197 WI-4

5. LOCATION REACTOR #2 ELV 190 + 217 AREA 15, 16 + 22

6. TYPE OF INSPECTION VISUAL + DIMENSIONAL



7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION BWS D1-1-72 REV 1-73 REV 2-74 C 91 REV G WQ 2/A = C 63 REV 1 ADDIT 1-5 FA #2 C 41A 115 WI-1 C 197 WI-6 C 197 WI-4 NCR 1090

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY _____

8411270245 840507
 PDR ADDCK 05000352
 G PDR

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED - ALSO SEE
 OCGI-1 REPORT # C 41A-493 dated 7-6-77, C 63-31
 dated 7-5-77 AND C-63-32 dated 7-5-77. C 63-33 dated 7-28-77
 AND REPORT # C 63-27 dated 4-5-77.

Distribution:
 3 - 3C Files
 1 - Original

KL Bialp 11-1-76

11. ENGINEER [Signature]