

RECORD COPY

APPL Ex 69

REFERENCE COPY

FILED C-63-17
DEC 23



FIELD INSPECTION REPORT

3. RECORD CONTROL
CONTROL NO. C-63-17
FILE NO. TPC-14-63-2


1. PROJECT NO. 8031 2. DATE 11/2/76 PAGE OF

4. ITEM INSPECTED PARTIAL RE INSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING O.C.T. INSPECTION PLAN.

C.543 W1-5

5. LOCATION RADWASTE ENCLOSURE FLW 191 AREA 20477

6. TYPE OF INSPECTION VISUAL & DIMENSIONAL



7. STANDARD/CODE/PROCEDURE/DRAWING/SPECIFICATION AWS D1-1-72 REV 1-73
REV 2-74 C91 REVS W'9-210 C63 REV 1 ADDIT 1-G, FA

C543 W1-5 NCA 1990

8. INSPECTION EQUIPMENT USED FILLET WELD GAGE

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY
B411270250 B40507
PDR ADCK 05000352
PDR

NOTE: FOR RE-INSPECTIONS ACCOMPLISHED - ALS
SEE OCGI-1 REPORT # C63-30 DATED 7-6-77, PARAGR 7.
ALSO SEE REPORT # C-63-22 DATED 4-5-77

L. Bilp 11-2-76

11. ENGINEER [Signature]