

APPLEX 73

C43 UGWA

REF 27



FIELD INSPECTION REPORT

3. RECORD CONTROL
CONTROL NO. C-63 20
FILE NO. ACC-1-63-17


1. PROJECT NO. 5031 2. DATE 1-17-77 PAGE 1 OF 1

4. ITEM INSPECTED TOTAL REINSPECTION OF WELDS ACCOMPLISHED ON THE FOLLOWING Q.C.T. INSPECTION PLANS.

C479 W-1-1 C477 W-1-3

5. LOCATION CONTROL ROOM ELEV 260' AND 250' AREA 9

6. TYPE OF INSPECTION VISUAL 4 DIMENSIONAL



7. STANDARD/CODE/PROCEDURE/DRAWING/SPECIFICATION AWS D-1-1-77 REV 1-73
REV 2-74 C91 REV 27 W O 210 C63 REV 1 ADDIT 1-7
FA #2 1-17-77 4/14

8. INSPECTION EQUIPMENT USED FILLET WELD GAUGE

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY

NOTE: FOR RE INSPECTIONS ACCOMPLISHED ALSO SEE OCGI-1 REPORT # C-63-72 DATED 4-5-77.

8411270271 840507
PDR ADOCK 05000352
G PDR

[Signature]
4-23-77

Distributor
Sales - CC File
Service - Engineer

[Signature] 11. ENGINEER *[Signature]*

1-17-77