

REF: 31

GEN. OCC




APPL. EX. 77 FIELD INSPECTION REPORT

1. RECORD CONTROL
CONTROL NO. C-63-24
FILE NO. SPC-63-23

1. PROJECT NO. 8131 2. DATE 7/5/77 PAGE 1 OF 1

4. ITEM INSPECTED Re-inspection of welds in ducts in ducts, Central inspection plan P-192-11-1-10. Areas to be inspected and Areas to be inspected full welds, beams 1A29 and 1A36 and part of 1A21, 1A4-5

5. LOCATION Reactor Unit #1 Flm 701'



MR-1990

6. TYPE OF INSPECTION Visual & Dimensional

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION AVIS D1.1-72, P1-73, E2-74
API Inspection Plan P-192-11-1-10 C-63/2 HD-1-3 FA2
Dwg. P-192/14

8. INSPECTION EQUIPMENT USED Fillet width gage & wire brush

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY _____

8411270351 840507
PDR ADOCK 05000352
G PDR

NOTE: FOR INSPECTIONS PREVIOUSLY ACCOMPLISHED.
ALSO SEE OCGI-1 REPORT # C-63-13 DATED 12-29-70.
ALSO FOR PREVIOUS INSPECTIONS SEE REPORT within 7-28
C-63-22 DATED 4-5-77

Distribution:
1 - CC File
1 - Engineer

K. B. ... 11. ENGINEER Engl. H. ...