




FIELD INSPECTION REPORT
RECORD COPY

2. RECORD CONTROL
CONTROL NO C63.25
FILE NO 206-1-63 24

1. PROJECT NO. 6031 2. DATE 7/5/77 PAGE 1 OF 1

4. ITEM INSPECTED Reinspection of welds in questioned Quality Control inspection plan C-200-W-1-1. Samples to corners and angles to embeds fillet welds, room 2489



102-1980

5. LOCATION Reactor Unit #1 Elev. 232'

6. TYPE OF INSPECTION Visual & Dimensional

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION ANSI D11-72, D1-73, D2-74
NAT Inspection Plan C-200-W-1-1 C-63/2 and 1-3 ASZ
Div. 200/14

8. INSPECTION EQUIPMENT USED fillet weld gage, wire brush

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY _____
8411270354 840507
PDR ADOCK 05000352
G PDR

NOTE: FOR INSPECTIONS PREVIOUSLY ACCOMPLISHED
ALSO SEE OGGI-1 REPORT C-63-19 dated 11-4-76
ALSO SEE REPORT C-63-22 dated 4-5-77
7-28-77