




APPL. EX. 79 FIELD INSPECTION REPORT

2. RECORD CONTROL
CONTROL NO. C-6326
FILE NO. SP-1263-3

1. PROJECT NO. 8021 2. DATE 7/5/77 PAGE 1 OF 1

4. ITEM INSPECTED Reinspection of welds in question in Externality Control inspection plan C-104-01-1-5. Applied to tanks and guides to embers fillet welds, rooms 1A17, 1B10, 1B11, 302, 1B13, 1B10, placed North-South and 1015 200.



11CR-1991

5. LOCATION Reactor Unit #1 Flr 201

6. TYPE OF INSPECTION Visual & Dimensional

7. STANDARD / CODE / PROCEDURE / DRAWING / SPECIFICATION ANSD 1.1-72, P2-73, P3-74
RT Inspection Plan C-104-01-1-5 C-63/2 Mid 1-3 F-12
Dwg C-194/7

8. INSPECTION EQUIPMENT USED Fillet wld. gage, wire brush

9. RESULTS OF INSPECTION: SATISFACTORY UNSATISFACTORY

10. ACTION TAKEN IF UNSATISFACTORY _____
B411290169 840507
PDR ADOCK 05000352
G PDR

Note: FOR PREVIOUS INSPECTIONS ACCOMPLISHMENTS - SEE ALSO
OGG-11 REPORT # C63-13 DATED 10-29-76. (See Draw 7-28-77)
ALSO REPORT C63-22 DATED 4-5-77