



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555

June 26, 1992

Docket No. 50-341

Mr. William S. Orser
Senior Vice President - Nuclear
Operations
Detroit Edison Company
6400 North Dixie Highway
Newport, Michigan 48166

Dear Mr. Orser:

SUBJECT: FERMI-2 INSPECTION OF LOW PRESSURE (LP) TURBINE DISKS AND NUMBER 3
LP TURBINE REPAIRS (TAC NO. M59614)

By letter dated August 17, 1990 and February 7 and October 10, 1991, you reported to the NRC pursuant to Facility Operating License No. NPF-43 Condition 2.C.(11) the results of three turbine disk inspections for the Fermi-2 LP turbines. The license condition requires the performance of ultrasonic inspection of LP turbine disks to monitor and detect the possibility of stress corrosion cracking (SCC). Additionally, in response to a February 4, 1992 teleconference, you provided additional information by letter dated April 29, 1992.

We have completed a review of your submittals. Based on our review, we have determined that you have satisfactorily completed License Condition 2.C.(11) for Fermi-2. The details of our review are contained in the enclosed Safety Evaluation. This completes our review under TAC No. M59614. If you have any questions please contact me at (301) 504-1341.

Sincerely,

Original signed by
Timothy G. Colburn, Sr. Project Manager
Project Directorate III-1
Division of Reactor Projects -III/IV/V

Enclosure:
As stated
cc: w/enclosure
See next page

OFFICE	LA:PDIII-1	PM:PDIII-1	PD:PDIII-1		
NAME	MShuttleworth	TColburn	LMarsh		
DATE	6/17/92	6/18/92	6/18/92	1/1	1/1

OFFICIAL RECORD COPY FILENAME: B:\59614.LP

9207060164 920626
PDR ADDCK 05000341
P PDR

NRC FILE CENTER COPY

Mr. William Orser
Detroit Edison Company

Fermi-2 Facility

cc:

John Flynn, Esquire
Senior Attorney
Detroit Edison Company
2000 Second Avenue
Detroit, Michigan 48226

Nuclear Facilities and Environmental
Monitoring Section Office
Division of Radiological Health
3423 N. Logan Street
P. O. Box 30195
Lansing, Michigan 48909

Mr. Stan Stasek
U.S. Nuclear Regulatory Commission
Resident Inspector's Office
6450 W. Dixie Highway
Newport, Michigan 48166

Monroe County Office of Civil
Preparedness
963 South Raisinville
Monroe, Michigan 48161

Regional Administrator, Region III
U.S. Nuclear Regulatory Commission
799 Roosevelt Road
Glen Ellyn, Illinois 60137

Mr. A. Cecil Settles
Director - Nuclear Licensing
Detroit Edison Company
Fermi Unit 2
6400 North Dixie Highway
Newport, Michigan 48166

DISTRIBUTION:

Docket File

NRC & Local PDRs

PDIII-1 Reading

Fermi Plant File

B. Boger

J. Zwolinski

L. Marsh

M. Shuttleworth

T. Colburn

OGC-WF

S. Sheng 7/D/4

ACRS (10)

W. Shafer, R-III

cc: Plant Service list

010013

DF01
110