



General Offices: 1945 West Parnall Road, Jackson, MI 49201 + (517) 788-0550

February 3, 1986

James G Keppler, Administrator Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-155 - LICENSE DPR-6 - BIG ROCK POINT PLANT -SPECIAL REPORT NO. 35: REACTOR CONTAINMENT BUILDING INTEGRATED LEAK RATE TEST - 1985


Special Report No. 35 entitled Reactor Containment Building Integrated Leak Rate Test is attached. This report is submitted in accordance with 10CFR50 Appendix J, Section V.B. Test results meet the required acceptance criteria. The next Integrated Leak Rate Test is tentatively scheduled for the 1989 refueling outage.

Ralph R Frisch Senior Licensing Analyst

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector - Big Rock Point

Attachment

8602110186 860203 PDR ADOCK 05000155





General Offices: 1945 West Parnall Road, Jackson, MI 49201 + (517) 788-0550

February 3, 1986

James G Keppler, Administrator Region III US Nuclear Regulatory Commission 799 Roosevelt Road Glen Ellyn, IL 60137

DOCKET 50-155 - LICENSE DPR-6 - BIG ROCK POINT PLANT -SPECIAL REPORT NO. 35: REACTOR CONTAINMENT BUILDING INTEGRATED LEAK RATE TEST - 1985

Special Report No. 35 entitled Reactor Containment Building Integrated Leak Rate Test is attached. This report is submitted in accordance with 10CFR50 Appendix J, Section V.B. Test results meet the required acceptance criteria. The next Integrated Leak Rate Test is tentatively scheduled for the 1989 refueling outage.

COPY

Ralph R Frisch (Signed)

Ralph R Frisch Senior Licensing Analyst

CC Director, Office of Nuclear Reactor Regulation Director, Office of Inspection and Enforcement NRC Resident Inspector - Big Rock Point

Attachment

0C0186-0016-NL04