



GPU Nuclear Corporation
 Post Office Box 480
 Route 441 South
 Middletown, Pennsylvania 17057-0191
 717 944-7621
 TELEX 84-2386
 Writer's Direct Dial Number:

August 29, 1988
 C311-88-2117

U. S. Nuclear Regulatory Commission
 Attn: Document Control Desk
 Washington, DC 20555

Dear Sir:

Three Mile Island Nuclear Station, Unit 1 (TMI-1)
 Operating License No. DPR-50
 Docket No. 50-289
 GPUN Response to Inspection Report (IR) 87-09

The purpose of this letter is to revise a commitment from our August 25, 1987 letter in response to Violation B from IR 87-09 which listed GPUN's long term planned actions regarding the makeup filter cubicle contamination event.

Our letter stated that the makeup filter 2A/B Cubicle interior would be decontaminated and repainted. From the photographs that had been taken earlier, the paint appeared to be cracking and flaking. However, following decontamination of the cubicle, the paint was found to be in good condition. Therefore, GPUN does not intend to repaint the makeup filter 2A/B Cubicle interior at this time. This change was discussed with the TMI-1 Senior NRC Resident Inspector who requested that this change to our commitment be noted in a letter.

Sincerely,

H. D. Hukill
 Vice President and Director, TMI-1

8809070325 880829
 PDR ADOCK 05000289
 G PNU

HDH/MRK

cc: J. Stolz
 R. Hernan
 R. Conte
 W. Russell

IE01
 1/0