

GPU Nuclear, Inc. Route 441 South Post Office Box 480 Middletown, PA 17057-0480 Tel 717-944-7621

October 28, 1998

1920-98-20206

U.S. Nuclear Regulatory Commission Attn: Document Control Desk Washington, DC 20555

Gentlemen:

Subject: Three Mile Island Nuclear Station, Unit 1 (TMI-1)

Docket No. 50-289

Operating License No. DPR-50

GPU Nuclear Cycle 12 Refueling (12R) Outage Once Through Steam Generator (OTSG) Tube Inspection Report with ASME NIS Data Reports for Inservice

Inspections (ISI) - Revision 1

GPU Nuclear submitted the Cycle 12 Refueling (12R) Outage Once Through Steam Generator (OTSG) Tube Inspection Report with ASME NIS Data Reports for Inservice Inspections (ISI) on January 12, 1998. Recently an error has been discovered in the number of inside diameter (ID) inter-granular attack (IGA) indications that were reported as remaining in service following the 12R Outage. Since the original submittal did not account for the tubes that were removed from service by plugging, the number of volumetric ID IGA indications remaining in service is fewer than that reported. The purpose of this letter is to correct the error and submit a revised NIS-1 Owners' Data Report for Inservice Inspections (attached) along with the revised pages of the "Report on the 1997 Outage 12R Eddy Current Examinations of the TMI-1 OTSG Tubing."

9811050167 981028 PDR ADOCK 05000289 G PDR

MRK Attachments

cc: Administrator, NRC Region I
TMI Senior NRC Resident Inspector
TMI-1 Senior NRC Project Manager
PA DOLI
Hartford Steam Boiler I&I Co.
File No. 97087

Sincerely,

James W. Langenbach

Vice President and Director, TMI

emy Wargenback

FORM NIS-1 OWNERS' DATA REPORT FOR INSERVICE INSPECTIONS

As required by the Provisions of the ASME Code Rules

- 1. Owner Metropolitan Edison Co. 2800 Pottsville Pike, Reading, Pennsylvania (Name and Address of Owner)
- 2. Plant Three Mile Island Nuclear Generating Station Route 441 South, Middletown, Pa. (Name and Address of Plant)
- 3. Plant Unit Unit 1 4. Owner Certificate of Authorization (if required) N/A
- 5. Commercial Service Date 09/02/74 6. National Board Number for Unit Reactor Vessel N-109
- 7. Components Inspected

Component or Appurtenance	Manufacturer or Installer	Manufac rer or der Serial 140.	State or Province No.	National Board No.
				/
	N	(A		
/				
/				
/				

Note: Supplemental sheets in form of lists, sketches, or drawings may be used provided (1) size is 8½ in. x 11 in., (2) information in items 1 through 6 on this data report is included on each sheet, and (3) each sheet is numbered and the number of sheets is recorded at the top of this form.

FORM NIS-1 (back)

8. Examination Dates 10/12/95 to 10/31/97 9. Inspection Interval from 1991 to 2001
10. Abstract of Examinations. Include a list of examinations and a statement concerning status of work required for current interval. This NIS-1 submittal is a correction for NIS-1 submittal approximation.
January 12, 1998. See attached Enclosure 1 for correction. 11. Abstract of Conditions Noted
See attached Enclosure, Revision 1, correction. 12. Abstract of Corrective Measures Recommended and Taken
Submitted in NIS-1 approved January 12, 1998.
We certify that the statements made in this report are correct and the examinations and corrective measures taken conform to the rules of the ASME Code, Section XI. Date OFTOBER 16-19 98 Signed MCR, NDE/131 SOR, By John & June Park John Spinder John S
Certificate of Authorization No. (if applicable) N/A Expiration Date N/A
CERTIFICATE OF INSERVICE INSPECTION
I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and/or the State or Province of Pa. and employed by H.S.B.I.&I.Company of Hartford, Ct. have inspected the components described in this Owners' Data Report during the period to 10/12/95 to 10/31/97, and state that to the best of my knowledge and belief, the Owner has performed examinations and taken corrective measures described in this Owners' Data Report in accordance with the requirements of the ASME Code, Section XI. By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations and corrective measures described in this Owners' Data Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.
Date OCT 16 1998 Commissions NB 54 78 (I) (N) Pa. 1887 Inspector's Signature National Board, State, Province and No.

TABLE, OF CONTENTS

			PAGE NO.	
I	INTR	INTRODUCTION		
П.	MET	METHODS		
	Α.	DATA ACQUISITION	6	
		Tube Bobbin Coil Examinations	7	
		2. Sleeve Bobbin Coil Examinations	7	
		 Motorized Rotating Pancake Coil (MRPC) Tube Examinations 	8	
		4. Plus Point Examinations of Sleeves	8	
	B.	B. DATA ANALYSIS PROCESS		
		Data Analyst Qualifications	8	
		Data Analysis Sequence	8	
		 Data Analysis Software 	9	
		 Recording of Indications 	9	
		5. Data Management	10	
	C.	DISPOSITION OF RESULTS	11	
		Inside Diameter IGA	11	
		Kinetic Expansion Region	11	
		Other Indications	15	
	D.	IN-SITU PRESSURE TESTING	15	
		Pressure Test Process	15	
		2. Tube Selection	16	
	E.	TUBE REMOVAL	17	
		1. Selection of Tubes	17	
		2. Pre-removal NDE	17	
		3. Removal Methods	18	
	F.	RECORDS	18	
III.	OUT	OUTAGE 12R EXAMINATION CATEGORIES AND RESULTS		
	A.	SCOPE SELECTION	21	
	B.	TUBE EXAMINATION RESULTS	30	
		 Γube Examinations (unexpanded region) 	30	
		 Kinetic Expansion Examinations 	44	
		 Lane/Wedge Examinations 	48	
		Rerolled Tube Examinations	48	
		5. Sleeve Examinations	48	
	C.	C. IN-SITU PRESSURE TESTING		
	D.	TUBE REMOVAL	50	
		ECT Results	50	