



Southern California Edison Company

SAN ONOFRE NUCLEAR GENERATING STATION

P. O. BOX 128

SAN CLEMENTE, CALIFORNIA 92672

H. E. MORGAN
STATION MANAGER

TELEPHONE
(714) 366-6241

October 18, 1988

U. S. Nuclear Regulatory Commission
Document Control Desk
Washington, D. C. 20555

Subject: Docket No. 50-362
Reactor Containment Building Integrated Leak Rate Test
San Onofre Nuclear Generating Station, Unit 3

An Integrated Leak Rate Test (ILRT) was performed at San Onofre Unit 3 during July 1988. The test was performed in accordance with the requirements of the Unit 3 Technical Specifications. Both the measured leak rate test and supplemental verification test met the acceptance criteria set forth in the Technical Specifications.

The enclosed ILRT report for San Onofre Unit 3 constitutes our final report and is being submitted pursuant to 10 CFR 50, Appendix J.

If additional information is required, please so advise.

Sincerely,

Enclosure

cc: J. B. Martin (Regional Administrator, USNRC Region V)
F. R. Huey (USNRC Senior Resident Inspector, Units 1, 2 and 3)

8810260031 881018
DR ADDCK 05000362
P PNU

A017
111