PF-35 and CPPR-117
86
2-7-86 Date Signed 2-10-86
Date Signed 2-//6/86 Date Signed

## SUMMARY

Scope: Routine, pre-operational inspection of Unit 2, totaling 60 hours for two inspectors on site. Areas inspected were Protected Area, (Alarms and Barriers), Vital Area Barriers, Assessment Aids, Lighting, and Compensatory Measures.

During the visit an additional item regarding Unit 1 was reviewed, the introduction of an unauthorized firearm into the protected area as reported by the licensee.

Results: The licensee was found to be in compliance except for the following:

Failure to conduct an adequate protected area search of a vehicle. (50-413/86-04-01)

8603280172 860325 PDR ADOCK 05000413 PDR

SAFEGUARDS INFORMATION

ENCLOSURE CONTAINS SAFEGUARDS INFORMATION UPON SEPARATION THIS PAGE IS DECONTROLLED.