



**Northeast
Nuclear Energy**

Rope Ferry Rd. (Route 156), Waterford, CT 06385

Millstone Nuclear Power Station
Northeast Nuclear Energy Company
P.O. Box 128
Waterford, CT 06385-0128
(860) 447-1791
Fax (860) 444-4277

The Northeast Utilities System

DEC - 3 1997

Docket No. 50-245
B16855

Re: 10CFR50.73(a)(2)(i)

U.S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, DC 20555


This letter forwards Licensee Event Report (LER) 97-040-00, documenting a condition that was discovered at Millstone Nuclear Power Station, Unit No. 1 on November 3, 1997 and a condition that was discovered on November 5, 1997. This LER is submitted pursuant to 10CFR50.73(a)(2)(i).

The following is Northeast Nuclear Energy Company's (NNECO's) commitment made within this letter. All other statements made within this letter are for information only.

B16855-1 NNECO commits that the specific surveillance procedures for the Rod Block Monitor, and the Isolation Condenser Steam Line High Flow and Condensate Line High Flow Indicators will be revised to incorporate the Instrument Check as specified in the Technical Specifications and implemented prior to startup for operating cycle 16.

Very truly yours,

NORTHEAST NUCLEAR ENERGY COMPANY


P. D. Hinnenkamp
Director, Unit Operations

9712050047 971203
PDR ADOCK 05000245
S PDR

Attachment: LER 97-040-00

cc: H. J. Miller, Region I Administrator
T. A. Easlick, Senior Resident Inspector, Millstone Unit No. 1
S. Dembek, NRC Project Manager, Millstone Unit No. 1

