

Point Beach Nuclear Plant 6610 Nuclear Rd., Two Rivers, WI 54241 (920) 755-2321

NPL 97-0746

December 11, 1997

Document Control Desk
US NUCLEAR REGULATORY COMMISSION
Mail Station P1-137
Washington DC 20555

Ladies/Gentlemen:

DOCKET 50-301
FILING OF OWNER'S INSERVICE INSPECTION SUMMARY REPORT
POINT BEACH NUCLEAR PLANT, UNIT 2

Attached is the Owner's Inservice Inspection Summary which is submitted in accordance with A3ME Section XI, IWA-6230. Included in this submittal is the Inservice Inspection Summary Report for Form NIS-1 and the Repair/Replacement Summary Report for NIS-2.

The information contained in the report reflects the inservice inspection activities during the first outage of the second period of the third 10-year interval, of Wisconsin Electric Power Company's Point Beach Nuclear Plant, Unit 2.

Sincerely,

Douglas F. Johnson

Manager,

Regulatory Service & Licensing

lad

Attachment

cc: NRC Resident Inspector NRC Regional Administrator

> 9712170473 971211 PDR ADOCK 05000301 9 FDR

A047

FORM NIS-1 OAM, ER'S REPORT FOR INSERVICE INSPECTIONS As required by the Provisions of the ASME Code Rules

Var er

1.	Owner Wisconsin Electric Power Company, 231 W. Michigan Ave., Milwaukee WI 53201 (Name and Address of Owner)				
2.	2. Plant Point Beach Nuclear Plant, 6610 Nuclear Road, Two Rivers, WI 54241 (Name and Address of Plant)				
3.	Plant Unit 2 4. Owner Cetafficate of Authorization (if required) Docket 50-301				
5.	Commercial Service Date 10/01/72 6. National Board Number for Unit N/A				

7. Components Inspected

Component or Appurtenance	Manufacturer or Installer	Manufacturer or Installer Serial No.	State or Province No.	National Board No
Pressurizer	Westinghouse	2T-1	U009979	******
A Steam Generator	Westinghorse		U009974	59
3 Steam Generator	WesGaghouse	******	U009975	60
Class 1 Piping Systems	Westinghouse	******	•••••	******
Class 2 Piping Systems	Bechtel	******	******	******
Class 3 Piping Supports	Becthel		******	******
B Residual Heat Removal HX	Joseph Oat Corp.	1529-6 1968	U009982	*****
A Reactor Coolant Pump	Westinghouse	2P-1A	*******	*
B Reactor Coolant Punp	Westinghouse	2P-1B		******

NOTE: Supplemental sheets in form of lists, skatches, or drawings may be used, provided (1) size is 8 ½ in. x 11 in., (2) information in items 1 through 6 on this report is included on each sheet, and (3) each sheet is numbered and the number of sheets is recorded at the top of this form.

FORM NIS-1 CONTINUED

- 8. Examination Dates 05/23/96 to 08/16/97, 9. Inspection Interval from 12/11/95 to 09/12/97
- 10. Applicable Editions of Section XI 1996 Addenda None
- 11. Abstract of Examinations. Include a list of examinations and a statement concerning status of work required for current interval.

Refer to attached Inservice Inspection Final Report, Section 3.0.

12. Abstract of Conditions Noted.

Refer to attached Inservice Inspection Final Report, Section 4.0.

13. Abstract of Corrective Measures Recommended and Taken.

Refer to attached Inservice Inspection Final Report, Section 4.0.

We certify that the statements made in this report are correct and the examinations and corrective measures taken conform to the rules of the ASME Code, Section XI.

Certificate of Authorization No. (if applicable) NRC Docket 50-301 Expiration Date N'A

Date December 11, 19 97 Signed Wisc Electric Power Contract By Sandan Brancher

CERTIFICATE OF INSERVICE INSPECTION

I, the undersigned, holding a valid commission issued by the National Board of Boiler and Pressure Vessel Inspectors and the State or Province of Wisconsin and employed by HSBII, Co. of Hartford CT, have inspected the components described in this Owner's Report during the period December 11, 1995 to September 12, 1997 and state that to the best of my knowledge and belief, the Owner has performed examinations and taken corrective measures described in this Owner's Report in accordance with the requirements of the ASME Code, Section XI.

By signing this certificate neither the Inspector nor his employer makes any warranty, expressed or implied, concerning the examinations and corrective measures described in this Owner's Report. Furthermore, neither the Inspector nor his employer shall be liable in any manner for any personal injury or property damage or a loss of any kind arising from or connected with this inspection.

Inspector's Signature Commissions 10731. WI-100057.

National Board, State, Province, and Endorsements