



# Pennsylvania Power & Light Company

Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

October 21, 1986

Mr. Paul Koval  
Chief, Operations Section  
Bureau of Water Quality Management  
Pennsylvania Department of Environmental Resources  
90 East Union Street, Second Floor  
Wilkes-Barre, PA 18701-3296

SUSQUEHANNA STEAM ELECTRIC STATION  
DISCHARGE MONITORING REPORT  
NPDES PERMIT NO. PA 0047325/SEPTEMBER 1986  
CCN 741326 FILE R9-8A  
PLE- 8804

Dear Mr. Koval:

Enclosed is a copy of the September 1986 Discharge Monitoring Report for Permit No. PA 0047325. The only noncompliances for September occurred at Outfall 072, Service and Administration Building Sump. The sump was discharged only once during the month with the total suspended solids average monthly limit of 30 mg/l being exceeded (33.3 mg/l) and the oil and grease average monthly limit of 15 mg/l also being exceeded (19.3 mg/l). These results were below daily maximum limits for this outfall. Construction activities in the vicinity of the sump caused rainwater runoff to be high in solids. Also, this discharge was not properly treated for oil and grease removal.

Corrective action to avoid future noncompliances from this outfall will include 1) paving the area in the vicinity of the sump to minimize collection of solids and 2) recycle of sump contents through oil and grease removal equipment prior to discharge.

If you have any questions, please call me at (215) 770-7889.

Respectfully yours,

Jerome S. Fields  
Senior Environmental Scientist-Nuclear

JSF:nsb

Enclosure

cc: EPA, Region III  
E. Adensam, NRC

8610270218 861021  
PDR ADOCK 05000387  
R PDR

IE25  
11