


Commonwealth Edison Byron Nuclear Station 4450 North German Church Road Byron, Illinois 61010 On D



August 7, 1987

LTR: BYRON 87-0837

Mr. A. Bert Davis Regional Administrator Office of Inspection and Enforcement Region III U. S. Nuclear Regulatory Commission Glen Ellyn, IL 60139

Dear Mr. Davis:

Attached is a report of the inservice inspections performed at Commonwealth Edison, Byron Unit 1 from February 17, 1987 through May 14, 1987. This report is submitted to you in compliance with the requirements of Article IWA-6000 of Section XI of the ASME Boiler and Pressure Vessel Code, 1980 Edition through the Winter 1981 Addenda. This report covers Byron Interval 1, Period 1, Outage 1 inspections.

If there are any additional questions, please contact Mr. D. F. Flowers at Byron Station.

herio


R. E. Querio Station Manager Byron Nuclear Power Station

REQ/DS/bf .

Attachment

cc:	F. Hornbeak	(w/o attachment)
	R. Tamminga	(w/attachment)
	K. Ainger	(w/o attachments)

#19/057



AUG 1 3 1987