

Wolf A



STATE OF NEW MEXICO
INSPECTOR OF MINES DEPARTMENT
2340 MENAUL, N.E., SUITE 106
ALBUQUERQUE, NEW MEXICO 87107

SAFETY FIRST



JOE D. LONGACRE, SR.
STATE INSPECTOR OF MINES

OFFICE TELEPHONE 842-3055
RESIDENCE PHONE 344-1129

RADIATION
REPORT OF INSPECTION

I. D. No. 2901645 - St. Anthony
Shaft No. 2 (United Nuclear Corporation)
(Name)

Typed May 23, 1978
May 11, 1978
(Date of Inspection)
M. J. Fletcher, Resident Manager
Manny Tarin, Safety Supervisor
(Company representative present at inspection)

Uranium
(Classification of Mine)

Valencia
(County in which located)

Pursuant to the Mining Laws of the State of New Mexico, Section 63-4-8, an inspection, as designated above, has been made. During this inspection the following was noted:

GENERAL INFORMATION

Date of previous radiation inspection: January 24, 1978

The operation is located from Highway 279 to Seboyeta, then Highway 334 east to the new Sohio shaft, then a dirt road approximately one mile east and one south to St. Anthony. The operation is owned and operated by United Nuclear Corporation.

Employment:

Total 32
Underground 20

Company Officials:

Jim Fletcher, Resident Manager
Manny Tarin, Safety Supervisor

Work Schedule:

Hours per day 8
Shifts per day 2
Days per week 5

Type of operation: mine development

Mining method: mine development

Principal product: uranium

Inspection Party: United Nuclear Corporation
Manny Tarin, Safety Supervisor

State of New Mexico
Howard Robison, Dust and Mine Gas Inspector

The shaft is completed to the 390 foot level and the 320 level is being developed. Ventilation is furnished by a 60 HP Hartzell surface fan blowing down the two shaft vent tubelines and a 60 H.P. Hartzell exhausting up the No. 1 borehole.

9304280317 780523
PDR ADOCK 04008907
C PDR

JOE D. LONGACRE, SR.
State Inspector of Mines

<u>Sample No.</u>	<u>Location</u>	<u>Ventilation</u>	<u>Men</u>	<u>Working Level</u>
1	5803 X S	5,000	4	nil
2	5806 RSW	40,000	1	nil
3	C.P. station-5805 X S	eddy	1	nil
4	5810 RWS	8,000	2	nil
5	5805 X S	40,000	2	nil


As all readings were nil, no mine index was prepared.

ACKNOWLEDGMENT

The courtesy and cooperation of all employees is gratefully acknowledged.

Inspected and Reported by:
Howard Robison
Dust and Mine Gas Inspector
Deputy Inspector of Mines

Approved


JOE D. LONGACRE, SR.
State Inspector of Mines