

COPES-VULCAN, INC.

P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

April 24, 1989

U.S. Nuclear Regulatory Commission Document Control Desk Washington, DC 20555

ATTENTION: Mr. E. William Brach,

Chief Vendor Inspection Branch

REFERENCE: Docket No. 99900080/88-01

Dear Mr. Brach,

As requested by your letter of April 11, 1989, enclosed are copies of the customer notification letters we issued last December. If you require any additional information, please do not hesitate to contact me.

Cordially,

COPES-VULCAN, INC.

James T. Dicarlo

President

JTD/pjg

Enclosures

8905250248 890424 PDR 0A999 EMVCOPES 99900080 PDC



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (£14) 774-3151 · FAX (£14) 774-2646 TRT-199140

December 6, 1988

Aerojet Nuclear Company P.O. Box 1845 Idaho Falls, ID 83401

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

CUST. PO NUMBER

CV JOB NUMBER

CV C/R NUMBER

P.O. Box 1845 Idaho Falls, ID 83401 Aerojet Nuclear Co.

S-7342 S-7215

7210-95221



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

American Water P.O. Box 6 Conshohocken, PA 19428

Rex Chainbelt Inc.

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Conshohocken, PA 19428 Rex Chainbelt Inc. P.O. Box 6 American Water

CUST. PO NUMBER

CV JOB NUMBER

CV C/R NUMBER

WZ-110543

7210-95220



COPES-VULCAN, INC.

P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Ametek, Calmec Division 8401 East Slauson Avenue Pico Rivera, CA 90600

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Ametek, Calmec Div. 8401 East Slauson Ave. Pico Rivera, CA 90660

CUST. PO NUMBER

16660

CV JOB NUMBER

NUMBER

CV C/R NUMBER

7820-97136 7820-97136 7620-97079



December 6, 1988

Argonne National Laboratories Argonne, IL 60439

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Acct. Dept. Argonne, IL 60439

CUST. PO NUMBER

IF-35773 IF-35773

CV JOB NUMBER

7720-97125

CV C/R NUMBER



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (B14) 774-3151 · FAX (B14) 774-2646 TRT-199140

December 6, 1988

Babcock & Wilcox P.O. Box 1260 Lynchburg, VA 24505

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

¢	1	ď
Ĺ	ž	d
ì	ž	H
Š	'n)
Ė		4
ì	į	2
ŧ	ŕ	ė

Power Generating Group 24505 Babcock & Wilcox Lynchburg, VA P.O. Box 1260

CUST. PO NUMBER

024036LM, 025720LF 025336LF

026308-LF 030072LN

026824-LN 026308LF 025337LF

026308LF

026827-LN 030071LN

025721LF 026308LF

0267047-LZ

026828-LF 026307-LZ

CV JOB NUMBER

CV C/R NUMBER

7110-14335 7310-95225

7310-95230 7520-95362

7310-95240

C/R 7310-95236)

7310-95236)

(C/R)

7520-95359

7310-95249 7310-95231

7520-95360

(C/R 7310-95248) (C/R 7310-95236)

7310-95248 7520-95361 7310-95226 7310-95236

7310-95262 7310-95239

(C/R 7310-95237)



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (B14) 774-3151 · FAX (B14) 774-2646 TRT-199140

December 6, 1988

Babcock & Wilcox 20 South Van Buren Barberton, OH 44203

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Babcock & Wilcox Co. 20 South Van Buren Barberton, OH 44203

CUST. PO NUMBER

02704712

CV JOB NUMBER

CV C/R NUMBER

7520-95336



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (B14) 774-3151 · FAX (B14) 774-2646 TRT-199140

December 6, 1988

Baltimore Gas & Electric P.O. Box 1472 Baltimore, MD 21203

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Purchasing & Stores Dept. P.O. Box 1472 Baltimore, MD 21203 Baltimore Gas & Elec.

CUST. PO NUMBER

31932-A

CV JOB NUMBER

7010-95030 7010-95031

CV C/R NUMBER



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Bechtel Corporation P.O. Box 303 Waterford, CT 06385

c/o The Millstone Point Company

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Bechtel Corporation c/o The Millstone Pnt Co. P.O. Box 303 Waterford, CT 06385

CUST. PO NUMBER

7604-M-405

CV JOB NUMBER 7110-95210

CV C/R NUMBER

Bechtel

CUST. PO NUMBER

CV JOB NUMBER

CV C/R NUMBER

PEH-7473

7310-95263



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Bechtel Power Corporation P.O. 101 Avoca, MI 48006

c/o Detroit Edison

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Ć	3	Ľ	,
í	i	Ž	1
i	ģ	Ė	
í	į		į
Ē	ŕ		
į	į	ľ	
•			
3	F		i

Bechtel Power Corp. c/o Detroit Edison P.O. Box 101 Avoca, MI 48006

CUST. PO NUMBER

9425-J-90-AC

CV JOB NUMBER

CV C/R NUMBER.

7620-97077



P.O. BOX 577 . LAKE CITY, PENNSYLVANIA 16423-0577 . PHONE (814) 774-3151 . FAX (814) 774-2646 TRT-199140

December 6, 1988

Bechtel Power Corporation Box 384 Berwick, PA 18603

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Bechtel Power Corp.
Attn: Office Manager
Box 384
Berwick, PA 18603

CUST. PO NUMBER

7410-95323

CV C/R NUMBER

CV JOB NUMBER

8856-J-67-AC 8856-J-67-AC

5323

(C/R 7410-95323)



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Bachtel Power Corporation Box 2167 Midland, MI 48640

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Bechtel Power Corp. Box 2167 Midland, MI 48640

CUST. PO NUMBER

7220-J-255A

CV JOB NUMBER

CV C/R NUMBER

(C/R 74~95327)

7820-95176



COPES-VULCAN, INC.

P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Bechtel Power Corporation Box 459 Russellville, AR 72801

c/o Arkansas Power & Light

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Bechtel Power Corp. c/o Arkansas P & L Box 459 Russellville, AR 72801

CUST. PO NUMBER

6600-M-2232A-AC

CV JOB NUMBER

7520-95366

(C/R 7410-95326) CV C/R NUMBER



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Carolina Power & Light Box 1551 5A3 Center Plaza Raleigh, NC 27602

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

Carolina Power & Light Box 1551 5A3 Ctr Plaza Raleigh, NC 27602

CUST. PO NUMBER

HBR-1095

CV JOB NUMBER

CV C/R NUMBER

7920-97150



P.O. BOX 577 LAKE CITY, PENNSYLVANIA 16423-0577 PHONE (614) 774-3151 FAX (814) 774-2646 TRT-199140

December 6, 1988

CE-KSB Pump Company P.O. Box 1007 Portsmouth, NH 03801

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

03801 CE-KSB Pump Co. P.O. Box 1097 Portsmouth, NE

CUST. PO NUMBER

N-77-0007 N-77-0007 N-77-0007 N-77-0007

CV JOB NUMBER

7720-95385 7720-95385 7720-95383 7720-95384

CV C/R NUMBER



P.O. BOX 577 . LAKE CITY, PENNSYLVANIA 16423-0577 . FHONE (814) 774-3151 . FAX (814) 774-2646 TRT-199140

December 6, 1988

Combustion Engineering P.O. Box 488 Windsor, CT 06095

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Combustion Engineering 06095 P.O. BOX 488 Windsor, CT

CUST. PO NUMBER

9870856

9770495 9770496 9900038

9872557

9203753

9872557

9770258 9402564

9870856 9402107 9770495 9870857

9803756

9872064

9770258 9770496 9870857 9101503

9872557 9402107

CV JOB NUMBER

7410-95325 7410-97063 7720-97104

7720-97102 7720-97103 6910-95002

7820-97137

7210-95224 7820-97137

7720-97116 7410-97063 7720-97104 7410-97062 7720-97102

6910-95003 7720-97105

7820-95393 7720-97116

7720-97103 7720-97105

7820-95394 7110-95121

7433-97062

CV C/R NUMBER

(C/R 7720-97102)

(C/R 7820-95394)

(C/R 7820-95394)

(C/R 7720-97104)

(C/R 7720-97102)



P.O. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Commonwealth Edison Box 767 Chicago, IL 60690

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Commonwealth Edison Purchasing Dept. Box 767 Chicago, IL 60690

CUST. PO NUMBER

719924

CV JOB NUMBER

7420-97064

CV C/R NUMBER

(C/R 6710-58359) (C/R 6710-58359)



P.O. BOX 577 - LAKE CITY, PENNSYLVANIA 16423-0577 - PHONE (B14) 774-3151 - FAX (B14) 774-2646 TRT-199140

December 6. 1988

Connecticut Yankee Atomic Power Box 270 Hartford, CT 06101

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

CUST. PO NUMBLR

Connecticut Yankee Atomic Pwr.431081 Purch. Dept. 431081 Box 270 Hartford, CT 06101

CV JOB NUMBER 7720-97123

CV C/R NUMBER

December 6, 1988

Consolidated Edison 4 Irving Place New York, NY 10003

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Accts Payable 4 Irving Place New York, NY Consolidated

CUST. PO NUMBER

-1981	-2443	7-24437	-2575	-1981	-2443
Edison	a)	90	10003		

-2443	-2575	-19819	-2443	-2493	-2493	-2443	-2493	-2575	-2493	
-	Pos	CT	-	Pho	P	Pho	5	~	-	

CV JOB 1

IBER

CV C/R NUMBER		(C/R 66-54080)	(C/R 66-54080)		
CV JOB NUMBER	7920-97146	7720-97118	7720-97118	7820-97128	7920-97146

(C/R 66-54080)

(C/R 66-54080)

7820-97128

7720-97119 7720-97117 7720-97124

7720-97117 7720-97124



December 6, 1988

CTI-Cryogenics 266 Second Avenue Waltham, MA 02154

Kelvin Park

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

CTI-Cryogenics Kelvin Park 266 Second Avenue Waltham, MA 02154

CUST. PO NUMBER

728228 728228 728228

CV JOB NUMBER

7720-95389 7720-97122 7720-97122

CV C/R NUMBER

(C/R 7720-95389) (C/R 7720-95389)



December 6, 1988

Daniel Construction Box 417 Dothan, AL 36302

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Daniel Construction Accounting Dept. Box 417 Dothan, AL 36302

CUST. PO NUMBER

7047-N-79583

CV JOB NUMBER

7720-95147

(C/R 73-95286) CV C/R NUMBER

December 6, 1988

Duquesne Light Company 435 Sixth Avenue Pittsburgh, PA 15219

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

USR/pjg

_
2
n
D
D
D
O.
DO
D C
CL
CLD
KED
MED
MED
MED
CHED
OMED
OMED
OMED
CARD
DOMED
TOMED
TOMED
TOMED
THOMED
CHOMPD
CHOMPD
CHOMPD
ICHOMPD
TOT
THUIL
THUIL
TOT

Duquesne Light Co. c/o Gen. Purchasing Agt 435 Sixth Avenue Pittsburgh, PA 15219

CUST. PO NUMBER

C00 3065 C00 3065

CV JOB NUMBER

(C/R 6910-95010) (C/R 6910-95010) CV C/R NUMBER

7720-97081



December 6, 1988

Foster Wheeler Corporation 110 South Orange Avenue Livingston, NJ 07039

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Foster Wheeler Corp. 110 South Orange Ave. Livingston, NJ 07039

CUST. PO NUMBER

N-20150-285-1045 N-20150-285-1045

CV JOB NUMBER

CV C/R NUMBER

7110-97039



December 6, 1988

General Electric Quad Citites Station Cordova, IL 61242

c/o Sargent & Lundy

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

General Electric c/o Sargent & Lundy Quad Cities Sta. Cordova, IL 61242

CUST. PO NUMBER

3620-131

CV JOB NUMBER

CV C/R NUMBER

6710-58363

CUSTOMER	General Electric A.P.E.D.

NUMB	
Z	75
PC	3-30
1	-AE
CUST	205

	-
	K
	田
- 11	SAL)
	\mathbf{z}
	2
	Z
	m
	-
	0
	5
	1
	0

(C/R 7110-95216) (C/R 7110-95216) CV C/R NUMBER.

7110-95217



December 6, 1988

General Electric Dresden Station Morris, IL 60450

c/o U.E. & C.

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

General Electric c/o U E & C Dresden Sta. Morris, IL 60450

CUST. PO NUMBER

3447-145

CV JOB NUMBER 6710-58359

CV C/R NUMBER

December 6, 1988

General Electric 175 Curtner Avenue San Jose, CA 95125

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

General Electric 175 Curtner Ave. San Jose, CA 95125

CUST. PO NUMBER

205-H0415 205-H1130 205-H0963 282-D-8408 205-H0415

CV JOB NUMBER

CV C/R NUMBER

6710-61950 6710-63058 6710-61949 7010-95029 6710-58568



December 6, 1988

Georgia Power Box 4545 Atlanta, GA 30302

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

CUSTOMLR

Georgia Power Box 4545 Atlanta, GA 30302

CUST. PO NUMBER

PEH-7473

CV JOB NUMBER

CV C/R NUMBER

7410-95330

(C/R 7310-95263)

December 6, 1988

Gulf General Atomic P.O. Box 60 San Diego, CA 92112

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

٤	3	4
į	ž	į
ì	2	4
Ġ	C	j
Ę	ļ	
ţ	1	١
t	i	j

92112 Gulf General Atomic P.O. Box 60 San Diego, CA 92112

CUST. PO NUMBER

952-501

CV JOB NUMBER

7110-95101

(C/R 6910-95006) CV C/R NUMBER



December 6, 1988

Knolls Atomic Power Laboratory Box 1072 Schenectady, NY 12301

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Knolls Atomic Power Lab Attn: Accts Payable Box 1072 Schenectady, WY 12301

CUST. PO NUMBER

NPD-79J-7870-AG NPD-79J-7870-AG

CV JOB NUMBER

7920-97151

CA

UMBER

CV C/R NUMBER



December 6, 1988

Long Island Lighting Co. 250 Old Country Road Mineola, NY 11501

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Long Island Lighting Co 250 Old Country Road Mineola, NY 11501

CUST. PO NUMBER

7920-95413

310735

CV JOB NUMBER

CV C/R NUMBER

(C/R 7510-95358)



COPES-VULCAN, INC.

PO. BOX 577 · LAKE CITY, PENNSYLVANIA 16423-0577 · PHONE (814) 774-3151 · FAX (814) 774-2646 TRT-199140

December 6, 1988

Northern States Power 414 Nicollet Mall Minneapolis, MN 55401

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Northern States Power 414 Nicollet Mall Minneapolis, MN 55401

CUST. PO NUMBER

Hiawatha 146

CV JOB NUMBER

CV C/R NUMBER

7010-95074



December 6, 1988

Omaha Public Power Distributors 836 Electric Building Omaha, NE 68102

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

CUSTOMER

Omaha Public Power Dist 41562

Purchasing Dept. 41562

836 Electric Bldg.

CUST. PO NUMBER

CV JOB NUMBER 7920-97139 7920-97139

CV C/R NUMBER (C/R 69-95003) (C/R 69-95003)



December 6, 1988

Pennsylvania Electric 1001 Borad Street Johnstown, PA 15907

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Pennsylvania Electric Manager of Purchasing 1001 Broad Street Johnstown, PA 15907

CUST. PO NUMBER

RSM-365 RSM-365

CV JOB NUMBER

CV C/R NUMBER

7110-97029

,



December 6, 1988

Portland General Electric Rainier, OR 97048

c/o Trojan Field Office

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Portland General Elec. c/o Trojan Field Office Rainier, OR 97048

CUST. PO NUMBER

N 00275 N00352

CV JOB NUMBER

CV C/R NUMBER

7110-95214

December 6, 1988

Power Authority, State of New York Box 8223 Philadelphia, PA 19101

c/o U.E. & C.

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Power Auth, State of NY c/o U E & C
Box 8223
Philadelphia, PA 19101

CUST. PO NUMBER

2465-77 2465-77 IP-P0-471 IP-P0-471

CV JOB NUMBER

7720-97320 97/20

NUMBER

C. C/R TUMBER



December 6, 1988

South Carolina Electric & Gas P.O. Box 764 Columbia, SC 29202

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

CUST. PO NUMBER

5436

CV JOB NUMBER

South Carolina E & G Acct. Dept. P.O. Box 764 Columbia, SC

6910-97016

CV C/R NUMBER

December 6, 1988

South Carolina Electric & Gas Box 8 Jenkinsville, SC 29065

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Q245435

CV JOB NUMBER

CUST. PO NUMBER

CV C/R NUMBER

7920-95408

South Carolina E & G
Box 8
Jenkinsville, SC 29065



December 6, 1988

Stone & Webster Box 63 Lycoming, NY 13093

c/o Niagara Mohawk

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

Lycoming, NY 13093 Stone and Webster c/o Niagara Mchawk Box 63

CUST. PO NUMBER

NMP-2-C051M

NMP2-C052M NMP2-C052M NMP2-C051M-6

CV JOB NUMBER

(C/R 7720-95350) CV C/R NUMBER 7620-97080 7720-95350 7620-97080

December 6, 1988

Stone & Webster 250 Old Country Road Mineola, NY 11501

c/o Long Island Lighting

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

c/o Long Island Lighting 250 Old Country Road Mineola, NY 11501 Stone and Webster

CUST. PO NUMBER


310730

CV JOB NUMBER

CV C/R NUMBER

7520-97071

(C/R 75-95358)



December 6, 1988

Stone and Webster P.O. Box 186 Shippingport, PA 15077

c/o Duquer & Light

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

c/o Duquesne Light P.O. Box 186 Shippingport, PA 15077 Stone and Webster

CUST. PO NUMBER

BV-32 BV-207

CV JOB NUMBER

CV C/R NUMBER



December 6, 1988

Tennessee Valley Ahtority 285 Haney Building Chattanooga, TN 37401

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Tennessee Valley Auth. Power Acctg Office 285 Haney Bldg Chattanooga, TN 37401

CUST. PO NUMBER

77K 3-820663-3 79P-J3-824303-2 72C-56-92697

CV JOB NUMBER

CV C/R NUMBER

7720-95279 7920-95198 7110-12286

.



December 6, 1988

Tennessee Valley Authority 400 Commerce Avenue (E9D88C) Knoxville, TN 37902

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

Accts Payable Section 400 Commerce Ave. (E9D83C) Knoxville, TN 37902 Tennessee Valley Auth.

CUST. PO NUMBER

79KJ3-821409-1 77K3-822067 76K-51-83081

CV C/R NUMBER

CV JOB NUMBER

7110-95207 7720-95388 7520-95337



December 6, 1988

The Cosmodyne Corporation 2920 Columbia Street Torrance, CA 90509

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

The Cosmodyne Corp. 2920 Columbia Street Torrance, CA 90509

CUST. PO NUMBER

48960

CV JOB NUMBER 7310-95246

CV C/R NUMBER



December 6, 1988

United Engineers & Constructors Box 700 Seabrook, NH 03874

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

CUSTOMER	CUST. PO NUMBER	CV JOB NUMBER	CV C/R NUMBER
United Engineers/Constructors 9763 Box 700 9763		7820-97134	(C/R 7720-97126)
Seabrook, NH 03874		7820-97135	
	9763.006-173-3	7720-97127	(C/R 7720-97126)
	9763.006-173-3	7720-97127	(C/R 7720-97126)
	9763.006-17334-11-77	7820-97134	(C/R 7720-97126)
	9763.006-173-3	7820-97135	(C/R 7720-97126)
	9763.006-173-3	7720-97126	



December 6, 1988

Wedco Corporation Box 809 Philadelphia, PA 19105

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

CUST. PO NUMBER

475-A-9321-05-

Purchasing - Eng. Components Box 809 Philadelphia, PA 19105 Wedco Corporation

CV JOB NUMBER

6910-95024

CV C/R NUMBER

December 6, 1988

Wedco Corporation Box 175 Buchanan, NY 10511

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

Wedco Corp. Materials Dept.

CUST. PO NUMBER

75B-EC-11562-41847 75B-EC-11562-41847

CV JOB NUMBER

(C/R 6710-55155) (C/R 6710-55155) CV C/R NUMBER

Box 175 Buchanan, NY 10511

CV C/R NUMBER	69-9501	9-950					(C/R 10-55155)					10-9	10-95	7110-9517	7310-9528	7110-9	7310-9528	7310-9529	7310-9528		7310-95	R 7110-9516		10-95	31	7310-95	7310-9525		7310-	0-952	95280	7110-	7310-9530	10-95	
CV JOB NUMBER	720-97	720-9711	810-6700	710-5820	0-5821	301	910-9502	00	43	910-9346	710-5841	110-9519	520-9535	110-9517	620-9537	110-9517	620-9537	310-9529	620-9537	310-9529	620-9537	110-9516	0-9538	110-9516	20-9538	310-9529	310-9525	310-9529	310-9525	7310-95289	0-9538	-9516	0-95	110-9516	10-95
CUST. PO NUMBER	-ccp	CP-9169	86058	58209	69821	86057	(No Charge)	86057	86057	-13	082	5-CCP-15743	5-CCP-18702	6-CCP-157335-	6-CCP-2520	6-CCP-15733	6-CCP-25201	6-CCP-18366	6-CCP-252016	6-CCP-18366	6-CCP-25201	6-CCP-1573	CC-25220	6-CCP-15732	5-CCP-25483	6-CCP-18366	6-CCP-17	6-CCP-18366	6-CCP-17832	6-CCP-1836	6-ccc-25222	46-CCP-15732	6-CCP-18364	6-CCP-15732	546-CCP-130012-BN
CUSTOMER	Westinghouse	stinghouse	Electr	Electr																										Westinghouse Electric	Westinghouse Electric	Westinghouse Electric	inghouse	-	Westinghouse Electric

CUST. PO NUMBER	ic 5	ric 546-CCF-294281	ic 546-CCP-15	ic 546-ACP-25220	ic	ric 546-CCF-157306-BN	ic	ic 546-CCP-183	ic 546-CCP-183	ic 54-6-CAK-9169	ic 546-CCF-15742	ric 546-CCP-130010-BN	ic	ic	ic 546-CCP-1836	ic 546-CCP-17832	ic 54-	ic 546-CCP-1836	ic 546-CCP-	ic 54-G-6616	ic 546-CCP-15732	ic	ic 546-CCP-15731	ic 546-CCF-2942	ic	ic 546-CCP-1574	ic 546-CCP-15731	ric 546-CCP-157433-BN	ic 546-CCP-15731	ic 546-CCP-1836	ic 546-CCP-15731	ric -273030		ric 546-CCP-18366	
CUSTOMER	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	stinghouse El	sti	sti	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr				Westinghouse Electr			Westinghouse Electr	Westinghouse Electr	nghouse	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	Westinghouse Electr	stinghouse Elect	1					

7323-BN 4281 7322-BN 2200-XN
BN BN BN
BN BN XN
BN BN BN
BN BN
BN BN

CUST. PO NUMBER	546-CCP-157436-BN 546-CCP-183648 BN 546-CCP-157432-BN 546-CCP-157302-BN 546-CCP-157301-BN	6-CCP-13/301- 6-CCP-183647 6-CCP-183626- 6-CCP-252013 6-CCP-252017 6-CCP-183625- 6-CCP-183624- 6-CCP-178320- 6-CCP-178320-	546-CCP-86057-BN 546-CCP-183645 BN 546-CCP-183668-BN 546-CCP-183668-BN 546-CCP-157423-BN 546-CCP-183655 BN 546-CCP-183656-BN 546-CCP-183666-BN 546-CCP-183666-BN 546-CCP-178327-BN 546-CCP-157431-BN 546-CCP-157431-BN 546-CCP-157437 546-CCP-178328-BN 546-CCP-178328-BN
CUSTOMER	Westinghouse Electric Westinghouse Electric Westinghouse Electric Westinghouse Electric Westinghouse Electric		Westinghouse Electric

	٤	2	4	
	Ç,	ä	ą	
*	٢	I	1	
	ì	٤	4	
	Ě	2)	
	ï	2	4	
	ķ	1	ą	
	ş	-)	
	r)	
	į	?		
	٦	w	,	

7110-95182

7110-95142

7310-95308

7310-95256

7110-95141 7310-95307 7110-95117 7620-95373

7310-95286

7620-95377

7310-95285

7620-95381 7310-95284

7310-95250

7110-95093

CV C/R NUMBER

110-951	310-95	-951	110-95	310-952	110-951	310-953	710-540	310-952	310-952	310-95	310-952	310-952	3	
1	1	(C/R	-	1	-	1	-	-	-	(C/R	-	(C/R	(C/R	

(C/R 10-55155)

7310-95250)	(C/R (C/R	7310-95258
		610-54
7110-95190)	(C/N	7110-95191
310-95250	(C/R	7310-95257
7110-95190)	(C/N	7110-95196
		6010-02000
7310-95290)	(C/R	7310-95296
310-95	(C/R	7310-95282
7310-95300)	(C/R	7310-95315
	(C/R	7410-95341
7110-95200)	(C/R	7110-95203
7310-95300)	(C/R	7620-95342
7310-95290)	(C/R	7310-95298
	(C/R	7310-95283
0-95	(C/R	7310-95305
-0	(C/R	7110-95092
		7520-95363
100400	176	1001

ď	,	,
í	ž	2
ì	٤	i
3	ü)
Ē		4
ļ	Į.	
ŧ	-)

| | Electric | lectr | Electric | Electric | Electric | Electric | Electric | Electric | Electric | Electric | Electric | | Electric |
|---|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|----------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|--------------|
| - | Westinghouse | | Westinghouse |

0	,
μ	ú
趈	d
C	а
TM	4
-	ı
2	¥
C)
Ã	d
4	
F.,	4
ъ.	
21	3
7110	2

546-CCP-183620-XN 546-CCP-252011 BN CN-005-187023 546-CCP-253079 BN (No Charge) 546-CCP-130-035 546-CCP-130-035 546-CCP-1332-BN 546-CCP-183665-BN 546-CCP-183665-BN 546-CCP-187321 546-CCP-17833-BN 546-CCP-17833-BN 546-CCP-187021-BN 546-CCP-187021-BN 546-CCP-187021-BN 546-CCP-187021-BN 546-CCP-187437 546-CCP-187437 546-CCP-187437 546-CCP-18743-BN 546-CCP-183443-BN 546-CCP-183443-BN 546-CCP-18742-BN 546-CCP-18742-BN 546-CCP-18742-BN 546-CCP-18742-BN 546-CCP-18742-BN 546-CCP-18742-BN 546-CCP-18742-BN	CCP-17833 CCP-15743 CCP-15743 CCP-15743 CCP-18365 CCP-17832 CCP-17832 CCP-18344 CCP-15742 CCP-15742	15732 18366 17833 15743 17833 18702	6-CCP-130-0 6-CCP-130-0 6-RI-116855 6-CCF-29428 6-CCC-25837	6-CCP-18362 6-CCP-25201 -005-187023 6-CCP-25307
--	--	--	---	--

CV JOB NUMBER

7310-95280 7620-95371 7610-95277 7620-95379 6910-95023 7310-95243 6910-95022 7820-95399 7310-95276 7310-95297

CV C/R NUMBER

310-9528	71-95160)	310-9528	610-5408	110-0516
0	(C/R	5	5	2

310-9529	110-95160	310-9529	310-9525
	(C/R 7	C/R	C/R

7310-95295 7520-95266 7310-95188

7410-95264

310-33530	110-95160	310	310-95250	110-95180	310-95250	110-95180	110-95160	310-95290	110-95190	110-95160	310-9530	310-9525
といい		(C/R 7										

7410-95268

7520-95267 7110-95181 7620-95319 7410-95269 7310-95316

7620-95381

6910-95020

7620-95375

7310-95273 7110-95202 7720-95390

7110-95183 7310-95272 7520-97072 7520-97073 7520-97072 7520-97073



December 6, 1988

Wisconsin Michigan Power Box 1007 Appleton, WI 54912

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays. Quality Control Manager

DSR/pjg

CUST. PO NUMBER

CV JOB NUMBER

CV C/R NUMBER

Wisconsin Michigan Power Box 1607 Appleton, WI 54912

A-80805



December 6, 1988

Wisconsin Public Service Box 700 Green Bay, WI 54305

Manager of Purchasing

Copes-Vulcan has determined that the valve weight and/or center of gravity referenced on some assembly drawings prior to 1980 may be incorrect. If the assembly drawings Copes-Vulcan provided your company includes this data and you require additional information, please contact Dale Mays, Quality Control Manager. On the attached sheet are Listed the job numbers on which Copes-Vulcan supplied valves to your company during the time frame in question.

Cordially,

Dale R. Mays Quality Control Manager

DSR/pjg

CUST. PO NUMBER 33772 Wisconsin Public Service Purchasing & Stores Box 700 Green Bay, WI 54305 CUSTOMER

CV JOB NUMBER

(C/R 6910-95009) (C/R 6910-95009) CV C/R. NUMBER