



SAFEGUARDS INFORMATION

UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION II
101 MARIETTA ST., N.W.
ATLANTA, GEORGIA 30323

Report Nos.: 50-269/89-20, 270/89-20, and 50-287/89-20

Licensee: Duke Power Company
422 South Church Street
Charlotte, NC 28242

Docket Nos.: 50-269, 50-270,
and 50-287

License Nos.: DPR-38, DPR-47, and
DPR-55

Facility Name: Oconee 1, 2, and 3

Inspection Conducted: June 26-30, 1989

Inspector: W. Tobin, Senior Safeguards Inspector

7/25/89
Date Signed

Approved by: D. R. McGuire, Chief
Physical Security Section
Nuclear Material Safety and Safeguards Branch
Division of Radiation Safety and Safeguards

7/25/89
Date Signed

SUMMARY

Scope:

This routine, unannounced inspection was conducted in the following areas: Physical Security Program for Power Reactors, specifically, Security Audit, Protected Area Barriers, Assessment, Access Controls, Alarm Stations, Testing, Maintenance and Compensatory Measures. The licensee's actions relative to NRC Notices, and prior Violations were also reviewed.

Results:

In the areas inspected, one apparently repetitive violation was identified:

- Failure to issue a picture badge prior to entry into the protected area.

NRC Notice 89-05 "Use of Deadly Force" - was closed and violation 88-10-01 "Bullet Resistant Barrier" was also closed.

The licensee continues the long term use of compensatory measures for its degraded assessment capability. Improvements were noted in alarm stations operations and security officer performance.

8908010033 890726
PDR ADOCK 05000269
Q FDC

SAFEGUARDS INFORMATION

Document transmitted herewith
contains sensitive unclassified
information. When separated from
enclosures, this document is decontrolled.