

[illegible]


A2	B2	B3	A3
B1	B4	B7	B5

LOCATION: MAIN CONTROL INSTRUMENT RACK ROOM

I certify that the image contained on this frame was made in the normal and regular course of business, on the date stated below and that it is an accurate reproduction of the document submitted to reprographics.

30X

(220) LOCATION IDENTIFICATION



CABLE SPREADING

2C180 2008 A3 (FOOT VIE

TERA
APERTURE
CARD

1	REVISED AS SHOWN	DATE	BY
2	REVISED AS SHOWN	DATE	BY
3	REVISED AS SHOWN	DATE	BY
4	REGRAB	DATE	BY
5	ISSUED FOR CONSTRUCTION	DATE	BY

No. _____ Date _____
 Revision _____
 Project _____

DECEMIL
 AND ASSOC. ENGINEERS

INDIANO PLANT UNIT 2
CONSUMER POWER COMPANY

DISTRICTS RAIL - UNIT 216
 BALANCE OF PLANT - (15)

	PROJECT NO. _____ 7220	DRAWING NO. _____ J-393(1) SFL 4	BY _____ 4
--	----------------------------------	--	----------------------

RIAS

8107220351

