



PEACH BOTTOM ATOMIC POWER STATION
 UNITS 2 AND 3
 UPDATED FINAL SAFETY ANALYSIS REPORT

Clamps installed on the replacement core spray sparger pipes structurally replacing welds at each of the four sparger T-box locations