

FEDERAL NOTIFICATION LETTER

Friday, March 05, 2021

**Director of FSME
Attn: GLTS
U.S. Nuclear Regulatory Commission
Washington, DC 20555-0001**

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

From General Licensee:

FedEx Ground
2460 NW Sundial Rd.
Troutdale, OR 97060

To Specific Licensee:

SRB Technologies, Inc.
2580 Landmark Drive
Winston-Salem, NC 27103
(336)-659-2610
Radioactive Materials License #034-0534-2


Date of Transfer: (Enter Date Disposal Box was shipped to Specific Licensee)	3/29/2021
--	-----------

Description of Device(s) Transferred:

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

Printed Name:	DONALD CROKER
Signature:	
Phone Number:	503.660.1714

FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT

VEOLIA USE ONLY

Sales Order #: 2217715
 Case #: 00047714
 Box 1 of 1

VEOLIA USE ONLY

RGA #: 998899
 RGA # Expiration Date: 6/2/2021
 UCN: 8E51385F-3G57834H
 Fedex Tracking #: 691191700135676

TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1. Shield Isolite Corp	SLX-60	10-15049	05-2010	20 years
2. Shield Isolite Corp	SLX-60	10-14843	05-2010	20 years
3. Shield Isolite Corp	SLX-60	10-15865	05-2010	20 years

Describe any damaged units:
 Please email pictures of damaged signs to pak.ts@veolia.com

1. Cracked bezel
 2. Missing Clear Cover, Legend, and front bezel
 3. Cracked Bezel

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

GENERATOR CERTIFICATION

Generator Signature: *Donald Crocker* Title: *Ops Manager*
 Print Name: *DONALD CROCKER* Date: *2/23/21*

VEOLIA INFORMATION – DO NOT WRITE IN THIS BOX

Date Received: *2-25-2021* Checked in by: *Angie Kung*