

# FEDERAL NOTIFICATION LETTER

Tuesday, July 13, 2021

**Director of FSME  
Attn: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001**

This letter is a notification per 10 CFR 31.5(c)(8) or corresponding State regulation indicating that a device containing radioactive material was transferred from a general licensee to a specific licensee. The following information is provided:

**From General Licensee:**

ABQC Corporation  
1602 S. First St.  
Milwaukee, WI 53204

**To Specific Licensee:**

SRB Technologies, Inc.  
2580 Landmark Drive  
Winston-Salem, NC 27103  
(336)-659-2610  
Radioactive Materials License #034-0534-2

<b>Date of Transfer:</b> (Enter Date Disposal Box was shipped to Specific Licensee)	7/20 <sup>mem</sup> /21
--	-------------------------

**Description of Device(s) Transferred:**

Exit signs containing tritium as per attached Inventory Form(s).

If there are questions or concerns, please contact me.

Sincerely,

<b>Printed Name:</b>	Mary Ellen Mortensen
<b>Signature:</b>	Mary Ellen Mortensen
<b>Phone Number:</b>	(262) 255-4468

**FEDERAL LETTER- MAIL TO USNRC WITHIN 30 DAYS OF SHIPMENT**

VEOLIA USE ONLY

Sales Order: 2227206  
Case #: 00059762  
Box 1 of 6

VEOLIA USE ONLY

RGA #: 999127  
RGA # Expiration Date: 9/28/21  
UCN: 7Q51384R-5S58129T  
Fedex Tracking #: 691191700139643

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	ISOLITE	880-12-6	11-32820	3/9/11	6.2
2.	ISOLITE	880-12-6	11-20554	2/5/11	6.2
3.	ISOLITE	880.12.1.1	none listed	none listed	25
4.	ISOLITE	880.12.1.1	none listed	none listed	25
5.	ISOLITE	880.12.1.1	none listed	none listed	25
6.	ISOLITE	880.12.1.1	none listed	none listed	25
7.	ISOLITE	880.12.1.1	none listed	none listed	25
8.	N/A none listed	N/A none	N/A none	N/A none	N/A none
9.	ISOLITE	880.12.1.1	none listed	none listed	25
10.	ISOLITE	880.12.1.1	none listed	none listed	25

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

All are damaged. Six signs have the frame bent off the right side, one is not intact. Two signs have faceplates not intact.  
- # 8 has no frame and/or faceplate.

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature: Mary Ellen Mortensen Title: Business Development Mgr.  
Print Name: Mary Ellen Mortensen on Behalf of ABC Corp. Date: 6/10/21

### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received: 6-11-21 Checked in by: Angie King

VEOLIA USE ONLY

Sales Order: 2227206  
Case #: 00059762  
Box 2 of 6

VEOLIA USE ONLY

RGA #: 999127  
RGA # Expiration Date: 9/28/21  
UCN: 2M51386N-9058113P  
Fedex Tracking #: 691191700139636

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	N/A	T-4001	N/A	N/A	25
2.	ISOLITE	880-12-6	11-16980	2/1/11	6.2
3.	ISOLITE	880-12-6	11-32819	3/9/11	6.2
4.	ISOLITE	880-12-6	11-32821	3/9/11	6.2
	ISOLITE	880-12-6	11-16982	2/1/11	6.2
	ISOLITE	880-12-6	11-16979	2/1/11	6.2
	ISOLITE	880-12-6	11-20549	2/5/11	6.2
	ISOLITE	880-12-1-1	CO 1225	1/1983	25
	ISOLITE	N/A	N/A	N/A	25
	ISOLITE	880-12-1-1	CO 1229	1/1980	25

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

n/a

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature: Mary Ellen Mortensen Title: Business Development Mgr.  
Print Name: Mary Ellen Mortensen on behalf of ABC Corp. Date: 6/10/21

### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received: 6-11-21 Checked in by: Angie Kung

VEOLIA USE ONLY

Sales Order: 2227206  
Case #: 00059762  
Box 3 of 6

VEOLIA USE ONLY

RGA #: 999127  
RGA # Expiration Date: 9/28/21  
UCN: 2I51388J-4K58101L  
Fedex Tracking #: 691191700139629

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	ISOLITE	880-12-6	11-20552	2/5/11	6.2
2.	ISOLITE	2040	A963475	6/99	11.5
3.	ISOLITE	none/n/a	none/n/a	none/n/a	25
4.	ISOLITE	880.12.1.1	CO1230	1/80	25
5.	ISOLITE	880-12-6	11-16983	2/1/11	6.2
6.	ISOLITE	880.12.1.1	CO1219	1/80	25
7.	ISOLITE	880-12-6	11-16983	2/1/11	6.2
8.	Saunders-Roe	none/n/a	ST-0664	none/n/a	21
9.	none/n/a	T-4001	63438	5/90	25
10.	none/n/a	CPI 700	1928	8/80	12.5

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

n/a

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature:

Mary Ellen Mortensen

Title:

Business Development Mgr.

Print Name:

Mary Ellen Mortensen on Behalf  
of ABC Corp.

Date:

6/10/21

### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received:

6-11-21

Checked in by:

Angie Kury

VEOLIA USE ONLY

Sales Order: 2227206  
Case #: 00059762  
Box 4 of 6

VEOLIA USE ONLY

RGA #: 999127  
RGA # Expiration Date: 9/28/21  
UCN: 8E51385F-3G58094H  
Fedex Tracking #: 691191700139612

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. **DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION.** Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	ISOLITE	880-12-1,1	none listed	none n/a	25
2.	ISOLITE	880-12-1,1	none n/a	none n/a	25
3.	ISOLITE	880-12-1,1	none n/a	none n/a	25
4.	ISOLITE	880-12-1,1	C01222	1/1980	25
5.	Saunders-Roe <sup>Developments</sup>	none/n/a	ST-0666	none	21
6.	ISOLITE	880-12-6	11-20555	2/5/11	6.2
7.	ISOLITE	880-12-6	11-32824	3/9/11	6.2
8.	ISOLITE	880-12-6	11-32827	3/9/11	6.2
9.	ISOLITE	880-12-6	11-20551	2/5/11	6.2
10.	ISOLITE	880-12-6	11-16981	2/1/11	6.2

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

n/a

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature:

Mary Ellen Mortensen

Title:

Business Development Mgr.

Print Name:

Mary Ellen Mortensen on behalf  
of ABC Corp.

Date:

6/10/21

### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received:

6-11-21

Checked in by:

Angie King

VEOLIA USE ONLY

Sales Order: 2227206  
Case #: 00059762  
Box 5 of 6

VEOLIA USE ONLY

RGA #: 999127  
RGA # Expiration Date: 9/28/21  
UCN: 1A51389B-6C58085D  
Fedex Tracking #: 691191700139605

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	ISOLITE	880-12-6	11-20550	2/5/11	6.2
2.	ISOLITE	880-12-6	11-16984	2/1/11	6.2
3.					
4.					
5.					
6.					
7.					
8.					
9.					
10.					

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

11-20550 & 11-16984 have their frame coming off on the right

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature:

Mary Ellen Martensen

Title:

Business Development Mgr.

Print Name:

Mary Ellen Martensen on behalf of ABQC Corp.

Date:

6/10/21

### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received:

6-11-21

Checked in by:

Gingie Kung

Sales Order: 2227206  
Case #: 00059762  
Box 6 of 6

RGA #: 999127  
RGA # Expiration Date: 9/28/21  
UCN: 5W51382X-8Y58076Z  
Fedex Tracking #: 691191700139599

## TRITIUM EXIT SIGN INVENTORY FORM

Record an inventory of the exit signs using the manufacturer label information on the back of the sign. Make sure that all information is legible. DO NOT REMOVE THE LABEL FROM THE SIGN. ALL FIELDS BELOW MUST BE FILLED OUT FOR EACH SIGN. DO NOT PUT ARROWS OR DITTO MARKS FOR REPETITIVE INFORMATION. Note: Double faced signs made by connecting two signs back-to-back should be counted as two signs even if there is one serial number on the housing. If you have one or more back-to-back signs, please list each one twice.

	DESCRIPTION/MFR.	MODEL NUMBER	SERIAL NUMBER	DATE OF MANUFACTURE	CURIES PER UNIT or LIFE RATING
1.	ISOLITE	ESD-12-6	11-16-986	2/1/11	6.2
2.					
3.					
4.					
5.					
6.					
7.					
8.					
9.					
10.					

Describe any damaged units:  
Please email pictures of damaged signs to  
pak.ts@veolia.com

I hereby certify that all information submitted on this form contains true and accurate descriptions of the exit signs.

### GENERATOR CERTIFICATION

Generator Signature:

Mary Ellen Mortensen

Title:

Business Development Mgr.

Print Name:

Mary Ellen Mortensen on behalf  
of ABC Corp.

Date:

6/10/21

### VEOLIA INFORMATION - DO NOT WRITE IN THIS BOX

Date Received:

6-11-21

Checked In by:

Angie King



N117 W18493 Fulton Drive - Germantown WI 53022

Director of FSME  
Attn: GLTS  
U.S. Nuclear Regulatory Commission  
Washington, DC 20555-0001

