

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

<p>1. LICENSEE/LOCATION INSPECTED:</p> <p>Ashok K. Gupta, M.D.</p> <p>610 East Twelve Mile Road Madison Heights, Michigan 48071</p> <p>REPORT NUMBER(S) 2021001</p>	<p>2. NRC/REGIONAL OFFICE</p> <p>Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352</p>
---	---

<p>3. DOCKET NUMBER(S)</p> <p>030-36604</p>	<p>4. LICENSE NUMBER(S)</p> <p>21-32524-01</p>	<p>5. DATE(S) OF INSPECTION</p> <p>September 24, 2021</p>
---	--	---

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Zahid Sulaiman, Health Physicist	Zahid M. Sulaiman <small>Digitally signed by Zahid M. Sulaiman Date: 2021.10.18 15:33:13 -05'00'</small>	
BRANCH CHIEF	Michael Kunowski, Chief, MIB	Michael A. Kunowski <small>Digitally signed by Michael A. Kunowski Date: 2021.10.18 15:48:37 -05'00'</small>	

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:

Ashok K. Gupta, M.D.

610 East Twelve Mile Road
Madison Heights, Michigan 48071

REPORT NUMBER(S) 2021001

2. NRC/REGIONAL OFFICE

Region III
U. S. Nuclear Regulatory Commission
2443 Warrenville Road, Suite 210
Lisle, IL 60532-4352

3. DOCKET NUMBER(S)

030-36604

4. LICENSE NUMBER(S)

21-32524-01

5. DATE(S) OF INSPECTION

September 24, 2021

(Continued)

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Ashok K. Gupta, M.D. 610 East Twelve Mile Road Madison Heights, Michigan 48071 REPORT NUMBER(S) 2021001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-36604	4. LICENSE NUMBER(S) 21-32524-01	5. DATE(S) OF INSPECTION September 24, 2021
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
-------------------------------	---------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
--------------------	-------------	---------------------	---------------------

Main Office Inspection Next Inspection Date: _____

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Ashok K. Gupta, M.D. 610 East Twelve Mile Road Madison Heights, Michigan 48071 REPORT NUMBER(S) 2021001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-36604	4. LICENSE NUMBER(S) 21-32524-01	5. DATE(S) OF INSPECTION September 24, 2021
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
-------------------------------	---------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
--------------------	-------------	---------------------	---------------------

Main Office Inspection Next Inspection Date: _____

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Ashok K. Gupta, M.D. 610 East Twelve Mile Road Madison Heights, Michigan 48071 REPORT NUMBER(S) 2021001	2. NRC/REGIONAL OFFICE Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352
---	---

3. DOCKET NUMBER(S) 030-36604	4. LICENSE NUMBER(S) 21-32524-01	5. DATE(S) OF INSPECTION September 24, 2021
--------------------------------------	---	--

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
-------------------------------	---------------------------

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
--------------------	-------------	---------------------	---------------------

Main Office Inspection Next Inspection Date: _____

Field Office Inspection _____

Temporary Job Site Inspection _____

PROGRAM SCOPE



Materials Inspection Record

1. Licensee Name: Ashok K. Gupta, M.D.		2. Docket Number(s): 030-36604		3. License Number(s) 21-32524-01	
4. Report Number(s): 2021001			5. Date(s) of Inspection: September 24, 2021		
6. Inspector(s): Zahid Sulaiman, Health Physicist		7. Program Code(s): 2201	8. Priority: 5	9. Inspection Guidance Used: 87130	
10. Licensee Contact Name(s): Ashok Gupta, RSO		11. Licensee E-mail Address: 8185AKG@gmail.com		12. Licensee Telephone Number(s): 248-541-9111	
13. Inspection Type:		14. Locations Inspected:		15. Next Inspection Date (MM/DD/YYYY):	
<input type="checkbox"/> Initial <input checked="" type="checkbox"/> Routine <input type="checkbox"/> Announced <input type="checkbox"/> Non-Routine <input checked="" type="checkbox"/> Unannounced		<input checked="" type="checkbox"/> Main Office <input type="checkbox"/> Field Office <input type="checkbox"/> Temporary Job Site <input type="checkbox"/> Remote		09/24/2026 <input checked="" type="checkbox"/> Normal <input type="checkbox"/> Extended <input type="checkbox"/> Reduced <input type="checkbox"/> No change	

16. Scope and Observations:
 This was an unannounced routine inspection of an outpatient cardiology clinic authorized to use byproduct materials for medical purposes permitted by 10 CFR 35.200. The nuclear medicine department was staffed with a part-time nuclear medicine technologist (NMT), who performed approximately 16 diagnostic doses monthly. The diagnostic procedures was cardiac stress test only using technetium-99m (Tc-99m). The licensee had a consultant physicist performed quarterly audits of the radiation safety program.

PERFORMANCE OBSERVATIONS

This inspection was consisted of tour of the clinic, interview with select licensee personnel, a review of select records, and an observation of security of the materials. At the time of inspection, NMT was not available and no diagnostic procedure was scheduled. The inspector observed the RSO conduct a physical inventory of sealed sources, and all sources were accounted for. The RSO discussed about the package receipt procedures, the end of the day daily and weekly area surveys, handling of radioactive waste and disposal procedures, with no issue noted. Through these discussion, the inspector found that the licensee personnel was knowledgeable of radiation protection principles, licensee procedures, and regulatory requirements.

The inspector reviewed the following records: quarterly program audits, dose calibrator linearity and accuracy tests, package receipts, waste disposal records, DOT Hazmat training, instrument calibration, sealed source leak tests and inventory, daily area surveys, and weekly wipe tests. The inspector reviewed dosimetry records for 2019 through July 18, 2021, indicating the maximum annual dose to be 58 mrem - DDE, and 182 mrem - SDE.

No violations of NRC requirements were identified as a result of this inspection.